

Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970

Tel: 6334 1182 Email: management@assist.com

Registration no. : SJS7947D / Volkswagen Scirocco 1.4L AT TSI 1372Q5

Date : 24-Jun-21

Estimate No. : AAS003_SJS7947D_SCIROCCO

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear fender RH	1436.90
2	1	Rear fender glass moulding RH	121.70
3	1	Rear fender inner shield RH	204.20
4	1	Rear upper arm RH	431.00
5	1	Rear lower arm RH	575.00
6	1	Rear trust arm RH	406.00
7	1	Rear trailing arm RH	372.00
8	1	Rear knuckle arm RH	684.00
9	1	Rear knuckle arm bearing RH	231.00
			4461.80

Less 5%	223.09
	4238.71

SPECIAL NETT ITEMS

1	1	Sundries	80.00
2	1	Rear fender glass primer and cleaner RH	100.00
3	1	Rear fender glass inner seal RH	100.00
4	1	Rear fender glass sealant RH	100.00
5	1set	Rear fender inner shield clips RH	50.00
6	1set	Rear bumper clips	80.00
7	1	Rear shock absorber RH	1050.00
8	1	Rear alloy rim RH R18	1200.00
9	1	Rear tyre RH R18	320.00
			3080.00

PART TOTAL	7541.80
-------------------	----------------

Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970

Tel: 6334 1182 Email: management@assist.com

Registration no. : SJS7947D / Volkswagen Scirocco 1.4L AT TSI 1372Q5

Date : 24-Jun-21

Estimate No. : AAS003_SJS7947D_SCIROCCO

S/N	Qty	Item	Amount
-----	-----	------	--------

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on rear accident area.	1500.00
2	1	Check wiring system after disconnect and connect.	80.00
3	1	R&R interior upholstery.	200.00
4	1	R&R RH rear fender glass,	180.00
5	1	R&R fuel tank.	320.00
6	1	R&R RH rear tyre and balancing.	80.00
7	1	R&R RH rear undercarriage.	280.00
8	1	To conduct wheel alignment.	150.00
9	1	To apply undercoating for rust roofing.	200.00
10	1	Spray painting on rear accident area.	1000.00
LABOUR TOTAL			3990.00

Total Parts and Labour Cost of Repair			11531.80
--	--	--	-----------------