



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE

Company Registration No. 201118055N

Kway Too Hwee
541 Hougang Ave 8, #03-1215 Singapore 530541
Contact : 98369385 66342112

ESTIMATE

Code : C102001

Date in : 28/06/2021

Vehicle Num. : SFV8040U

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11321310/L15B5571348

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
LH side skirt assy	1	334.10 <i>nn x</i>	334.10
Rear bumper	1	1161.50 <i>cut</i>	1,161.50
Rear bumper reflectors LH	1	181.00 <i>nn x</i>	181.00
Rear bumper side garnish LH	1	259.20 <i>de</i>	259.20
Rear bumper side retainers LH	1	44.00 <i>na</i>	44.00
Rear bumper side spacer LH	1	27.00 <i>na</i>	27.00
Rear fender inner cowling LH	1	157.50 <i>de</i>	157.50
Rear fender inner garnishes LH	1	240.90 <i>nn x</i>	240.90
Rear fender LH	1	982.80 <i>Rx</i>	982.80
Rear LH door panel	1	1262.40 <i>Rx</i>	1,262.40
Rear wheel arch garnish assy LH	1	280.80 <i>de</i>	280.80
Subtotal before discount		1930	4,931.20
Percentage discount 20%		1544	986.24
Sub-total 1			3,944.96
Rear Bumper Clips (Set) (SN)	1	50.00 <i>30</i>	50.00
Rear Fender Inner Clips (SET) (SN)	1	50.00 <i>20</i>	50.00
Subtotal before discount			100.00
Percentage discount 0%		50	0.00
Sub-total 2			100.00
Parts-total			4,044.96



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	30. 150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600 1,000.00
Labour Total	1230 2,150.00
Parts & Labour Total	6,194.96

page 2

1544
 50
 1230
 'up' 29/6/21 @ 11/15 2824
 c/s Resurvey after repair c/s \$2250
 tariff @ 11/15 @ 24 days
 4-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: