

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref: CS3/GRB21005844/R1tf3-1	
64 CECIL STREET		Date: 28/06/2021	
#05-02 IOB BUILDING SINGAPORE 049711		Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 6013M	Veh. Inspected	FBR 9774Y
Policy No.	D21MFL0000447	Coverage (\$)	0.00
Claim No.	MFL2021D0002143	Excess (\$)	0.00
Assign From	CARINE KEK PHER SER	Assign Date	28/06/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/05/2021	Inspection Date	05/07/2021
Survey held at	61 WOODLAND INDUSTRIAL PARK E9 #01-14 E9 PREMIUM		
Repairer	GP MOTORING PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			