NOTE: TO B	E COMPLET	ED BY SURVEYOR
------------	-----------	----------------

TEAM	
------	--

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:		SLK7924M (Insd veh)					Model:		MAZDA 5 2.0 SP.6EAT SUNROOF (A)		
		SLE7511C (TP veh)									
Date	f Accident: 26/06/2021										
01.1	10 0 111	<u> </u>	-			Ī		1			
	al Sum Settlement	:	[] Ye			[X] No				
Repair Estimate						\$,364.00			
Final Repair Cost						\$	3,905.50				
	of Use				<u>:</u>	_		600.00	6.00 days at \$100.00 per day		
	al (if any)				:			0.00	days		
	GIA Search Fee				:			2.00			
Other	S:				:			0.00			
					:						
	Settlement Sum				:			4,507.50			
	ird Party Workshop GIA I] YES	[X]	NO	()				
A)	For Non GIA Registere		<u>:</u>				Agreed Liability		(%)		
B)	For GIA Registered Wo								BOLA Scenario No:		
	BOLA Liability:						Assessed Liabil	,	(%)		
	* Assessed Liability to be	e filled only fo	or chain	collisions a	and for cas	es whe	re BOLA does not a	apply.			
Rema	arks										
	ent Instruction: Payee's										
1)	Hock Wah Motor Works	shop Pte Ltd					: \$			4,507.50	
2)							: \$				
3)							: \$				
	JOANNI	E LEE KHAN	G MIN				19 Oct 2021				
	LKK Auto	Consultants	Pte Ltd	d			Date	_			
	LKK Auto	Consultants	Pte Ltd	d			Date				

10/19/21, 11:51 AM Preview