



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007117/Avf3n2	Date: 25/05/2022
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMV 7924T	Veh. Inspected	SLK 6699U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010655/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	29/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLB200	c.c	1332	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	W1N2476872W049984	Colour	GREY	
Odometer	7958 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	PIRELLI	6 mm	
L/H Front Tyre	235/55 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/55 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/55 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2021	Inspection Date	29/06/2021	
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	