



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21005512/R1tf3e2-1 Date: 26/07/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1475L	Veh. Inspected	JJG 9813	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024534	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	29/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA INNOVA	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	PN111NV4008602142	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50Z R17	APLUS	6 mm	
L/H Front Tyre	225/50Z R17	APLUS	6 mm	
R/H Rear Tyre	225/50Z R17	APLUS	6 mm	
L/H Rear Tyre	225/50Z R17	APLUS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2021	Inspection Date	07/05/2021	
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	