ORTDELGRO ENGINEERING PTE LTD

SHA5965H

DATE 25.06.21 CHIANG/CHINA

Y	Parts Description/ Labour	Туре	Unit Price	Amount
				\$458.60
-1	REAR BUMPER SE	100		\$552.60
1	REAR BUMPER LOWER COVER SOL	Alexander .		\$318.80
1	REAR BUMPER REINFORCEMENT			\$82.70
7/1	REAR BUMPER TOW COVER	1 5000		\$55.00
1	REAR BUMPER REFLECTOR RH	12.0		\$112.70
1 F	REAR BUMPER SIDE RETAINER /RH X \$20			\$22.00
10 F	REAR BUMPER CLIP MC		1033.W	\$1,602.40
	SUB TOTAL	7 7 9 4	201	\$400.6
	25.00%		John	\$1,201.8
	DISCOUNTED TOTAL	120-11	774.90	
				\$100.0
3.94	EAR FENDER ADVERTISEMENT RH		120	\$50.0
200	EAR BUMPER ADVERTISEMENT W			\$135.
1180	UMPER REVERSE SENSOR 7. XST			\$285.
			TANGE 18	
La	bour Charge	N.S.		
Pa	nel Beating	N-	640 3	50 \$500
Spi	ray Painting Charge	13 1 1	-	250 \$600
Che	eck wiring and lighting	1000		**× \$60
Rer	move/Refix Reverse Sensor	1000	The second	40 550
3	TOTAL LABOUR	line-1		\$1,320
	ESTIMATE TOTAL	TO THE		\$2,807
			TALL WE SEE THE	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

> LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

774.90 Rasue
150.00 Hp 90010068
1564.90 3 days
1564.90 Hs
1251.92 28/06/21@1630
Hs-1,250 Resy after
report