

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0526/2021/TF
DATE : 24-Jun-21
WIP : 32825

Veron

~~\$548576~~

SDY

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : CHENG KHENG BOON
ADDRESS : 14 JALAN SHAER

SINGAPORE 769360
TELEPHONE : HP +65 93870509
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210053600
VEHICLE NO : SGL 69 C
MODEL CODE : E TRON SPORTBACK ADVANCED 50 QUATTRO
MODEL YEAR : 29/5/2021
ENGINE NO : EAS 137438
CHASSIS NO : WAUZZZGE6MB032865
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Jun-21
PLACE OF ACCIDENT : CTE BEFORE BRADELL EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGL 69 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	✓✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	2,000.00	500 ✓ 600
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,500.00	1000 ✓ 950 = 550 + 400
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓✓
TOTAL LABOUR CHARGES		:	\$ 7,972.00	

55, UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 69 C

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Regis</i>	1	\$	2,724.00	*
2	FRONT BUMPER LOWER SIDE TRIM - LH / RH	2	\$	116.00	*
3	FRONT BUMPER FIXING PARTS	1	\$	631.00	*
4	FRONT BUMPER CLOSING ELEMENT - CENTER <i>2</i>	1	\$	222.00	* 177.60
5	FRONT RADIATOR GRILLE BRACKET - LH <i>Not new</i>	1	\$	30.00	? X
6	FRONT BUMPER COVER - LH / RH <i>new</i>	2	\$	70.00	*
7	FRONT RADIATOR GRILLE FOAM <i>new</i>	2	\$	246.00	? X
8	FRONT BUMPER PLASTIC FORM STRIP <i>new</i>	1	\$	120.00	? X
9	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	1	\$	254.00	*
10	FRONT BUMPER INNER GRILLE - CENTER <i>Damaged</i>	1	\$	153.00	? 122
11	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$	210.00	*
12	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$	182.00	*
13	FRONT BUMPER IMPACT PROTECTION (SILVER) <i>new</i>	1	\$	807.00	*
14	FRONT BUMPER SIDE SPOILER - LH / RH <i>new</i>	2	\$	314.00	*
15	FRONT RADIATOR AIR GUIDE - UPPER / LOWER CENTER - LH / RH <i>new</i>	6	\$	420.00	*
16	FRONT RADIATOR GRILLE <i>combined</i>	1	\$	2,086.00	✓ 1668.80
17	FRONT RADIATOR GRILLE CAMERA COVER <i>new</i>	1	\$	136.00	*
18	FRONT RADIATOR GRILLE CAMERA BRACKET <i>new</i>	1	\$	93.00	*
19	FRONT RADIATOR GRILLE CAMERA SECURING PLATE <i>new</i>	1	\$	84.00	*
20	FRONT RADIATOR GRILLE LOGO COVER <i>Not new</i>	1	\$	62.00	? X
SUB TOTAL SPARE PARTS			:	\$ 8,960.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 69 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT RADIATOR GRILLE CLOSING ELEMENT (GREY) <i>2 for</i>	1	\$ 221.00	*
22	FRONT RADIATOR GRILLE COVER (GREY) - LH / RH	2	\$ 275.00	*
23	FRONT RADIATOR GRILLE CAMERA <i>new</i>	1	\$ 906.00	*
24	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 577.00	+
25	FRONT BUMPER TEMPERATURE SENSOR	1	\$ 59.00	+
26	FRONT BUMPER CROSS MEMBER - LOWER	1	\$ 425.00	+
27	FRONT BUMPER CARRIER <i>new</i>	1	\$ 1,362.00	? X
28	FRONT BUMPER BRACKET <i>new</i>	1	\$ 430.00	? X
29	FRONT RADIATOR GRILLE COVER - TOP / BOTTOM <i>cracked</i>	2	\$ 210.00 105.84	
30	FRONT RADIATOR GRILLE BRACKET - LH / RH <i>cracked</i>	2	\$ 154.00	✓ X
31	WARNING SIGN STICKER <i>new</i>	1	\$ 19.00	✓ 14.80
32	FRONT PARKING AID SENSOR - INNER <i>new</i>	2	TBC	✓
33	FRONT PARKING AID SENSOR SEAL RING	4	\$ 14.00	*
34	FRONT BUMPER SPOILER - LH / RH <i>new</i>	2	\$ 190.00	+
35	FRONT HEADLIGHT - LH / RH <i>new</i>	2	\$ 16,284.00	+
36	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,030.00	✓ 827.20
37	E-TRON EMBLEM <i>new</i>	2	\$ 212.00	*
38	FRONT NO. PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60
39	SUNDRIES <i>new</i>		\$ 300.00	? 10.56
TOTAL SPARE PARTS		:	\$ 31,688.00	
TOTAL LABOUR CHARGES		:	\$ 7,972.00	
GRAND TOTAL		:	\$ 39,660.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
 SURVEYED DATE : *29/06/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 03 Days 04 Days.*
H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT