



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21007182/T1qf3e2	
			Date: 19/08/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 7910T		Veh. Inspected	SMH 2866J
Policy No.			Coverage (\$)	0.00
Claim No.	21/21/21/VP05/024698		Excess (\$)	0.00
Assign From	ONG LI LI		Assign Date	30/06/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED HYBRID		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2019
Chassis No.	GB71083049		Colour	RED
Odometer	193551 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		195/60 R15	WEST LAKE	6 mm
L/H Front Tyre		195/60 R15	WEST LAKE	6 mm
R/H Rear Tyre		195/60 R15	WEST LAKE	6 mm
L/H Rear Tyre		195/60 R15	WEST LAKE	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2021		Inspection Date	30/06/2021
Survey held at	OOHRAI RENTAL PTE LTD 8 KAKI BUKIT AVENUE 4, #06-31, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	