

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN		Ref:	CS/CTI21007203/Uvc		
	3 ANSON ROAD # SPRINGLEAF TOV		Date:	01/07/2021		
				Code:	СТІ	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJY 1389Y	Veh. Inspected		GBL 1688Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D202691/C02/SJY1389Y /THAMYL	Excess (\$)		0.00	
	Assign From	PAULINE THAM	Assign Date		01/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	08/05/2021	Inspection Date	е	01/07/2021	
	Survey held at	ETHOZ GROUP LTD				
		22 TAMPINES STREET 92 SINGAPORE 528876				
5a.	Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						