



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8670X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH @\$35.60	SERVICEABLE	71.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
1	BOOTLID EMBLEM I-40	NECESSARY	67.90	67.90
1	BOOTLID EMBLEM CRDI	NECESSARY	52.40	52.40
1	BOOTLID H EMBLEM	NOT NECESSARY	63.10	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUMPER REFLECTOR LH/RH @\$32.00	SERVICEABLE	64.00	-
1	REAR BUMPER UNDER COVER	SCRATCHED	228.00	228.00
	LESS 20% DISCOUNT		-420.60	-295.26
			1,682.40	1,181.04
<u>NETT ITEMS</u>				
1	REAR REVERSE SENSOR (N)	SERVICEABLE	135.70	-
	LESS 10% DISCOUNT		-13.57	-
			122.13	-
<u>SPECIAL NETT ITEMS</u>				
1	BOOTLID TEL NUMBER STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID COMFORTDELGRO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER MAT (SN)	SCRATCHED	50.00	50.00
			160.00	160.00
<u>LABOUR</u>				
	PANEL BEATING.		560.00	280.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	40.00
	TUFF KOTE.	NOT NECESSARY	60.00	-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK LIGHTING & WIRING.	NOT NECESSARY	60.00	-
			1,340.00	820.00
GRAND TOTAL			3,304.53	2,161.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,700.00

Report Ref No. NS/INC21007222/R1vcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.