

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
JIANG
CHUNKAI
51 STRATHMORE AVENUE
#20-193
Singapore 140051

Document no.
Document date 01-07-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021024522/ 1
Job order date 30-06-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKW4944Z	5G13GZ	30-10-2015	VWVZZZAUZFW356593	Golf 1.4 CLBMT 90 TSI D7F	18,731

REPAIR LIMIT:

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5G0853687 2ZZ	Inscription Bright Chrome X	1	pcs.	80.16	#1	80.16	85.77
	REAR LOGO - GOLF						
5G0853675APCW	Inscription Pure White/Po X	1	pcs.	83.25	#1	83.25	89.08
B	LOGO - BLUEMOTION						
5G0853675A JZQ	Inscription Chrome Shine/ X	1	pcs.	84.47	#1	84.47	90.38
	LOGO - TSI						
5G6807417APGRU	Cover For Bumper Primed X R	1	pcs.	1,303.20	#1	1,303.20	1,394.42
	REAR BUMPER						
5G6807568D 9B9	Rear Diffuser Satin Black ?	1	pcs.	336.18	#1	336.18	359.71
5G0807305D	Bumper ?	1	pcs.	650.77	#1	650.77	696.32
	REAR REINFORCEMENT						
5G6807863C	Attachment Strip ?	1	pcs.	69.96	#1	69.96	74.86
	REAR BUMPER CTR BRACKET						
5G6807393A	Guide Piece ?	1	pcs.	40.52	#1	40.52	43.36
	LHR BUMPER BRACKET (UPPER)						
5G6807394A	Guide Piece ?	1	pcs.	40.52	#1	40.52	43.36
	RHR BUMPER BRACKET (UPPER)						
5G6807393	Guide Piece ?	1	pcs.	40.52	#1	40.52	43.36
	LHR BUMPER BRACKET (SIDE)						
5G6807394	Guide Piece ?	1	pcs.	40.52	#1	40.52	43.36
	RHR BUMPER BRACKET (SIDE)						
1K8943021	License Plate Light	2	pcs.	40.85	#1	81.70	87.42
5G0807217BNGRU	Cover For Bumper Primed - 00	1	pcs.	1,313.60	#1	1,313.60	1,405.55
	FRT BUMPER						
5G0807109AL	Impact Beam ?	1	pcs.	683.62	#1	683.62	731.47
	FRT REINFORCEMENT						
5G0807248F	Foam Insert ?	1	pcs.	45.29	#1	45.29	48.46
	FRT BUMPER FOAM						
5G0807723D	Support Part ?	1	pcs.	59.04	#1	59.04	63.17
	BUMPER INNER BRACKET LH						
5G0807049A	Guide Piece ?	1	pcs.	22.75	#1	22.75	24.34
	BUMPER SIDE BRACKET LH						
5G0807050A	Guide Piece ?	1	pcs.	22.75	#1	22.75	24.34
	BUMPER SIDE BRACKET RH						
5G0853651G ZLL	Radiator Grille Satin Bla - cut	1	pcs.	524.74	#1	524.74	561.47
5G0853677 9B9	Cooling Air Grill Satin B ?	1	pcs.	149.05	#1	149.05	159.48
	BUMPER CTR LOWER GRILLE						
5G0805705G	Guide ?	1	pcs.	51.97	#1	51.97	55.61
	FRT BUMPER CTR BRACKET						
5G0805567	Support For Lock Carrier X	1	pcs.	46.50	#1	46.50	49.76
5G0805931	Cross Support	1	pcs.	38.96	#1	38.96	41.69
	H/LAMP TOP PANEL LH X						

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page

2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
JIANG
CHUNKAI
51 STRATHMORE AVENUE
#20-193
Singapore 140051

Document no.
Document date 01-07-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021024522/ 1
Job order date 30-06-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKW4944Z	5G13GZ	30-10-2015	WVWZZZAUZFW356593	Golf 1.4 CLBMT 90 TSI D7F	18,731

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G2941005E	Twin Halogen Headlamps X LH	1	pcs.	764.37	#1	764.37	817.88
6R0973735	Flat Contact Housing X H/LAMP WIRE HOUSING	1	pcs.	21.07	#1	21.07	22.54
	LABOUR REAR	81	pcs.	840.00	#1 840	2,520.00	2,696.40
	SPRAY PAINT REAR	81	pcs.	800.00	#1 800	2,400.00	2,568.00
	LABOUR FRT	81	pcs.	840.00	#1 840	2,520.00	2,696.40
	SPRAY PAINT FRT	81	pcs.	800.00	#1 800	2,400.00	2,568.00
	FRT NUMBER PLATE BT	1	pcs.	80.00	#1	80.00	85.60
	REAR NUMBER PLATE BT	1	pcs.	80.00	#1	80.00	85.60
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	AIG DIRECT SETTLEMENT						
	DOA: 30/06/2021						
	TP VEH: SKX8294J						
	SURVEY BY:						

Quotation valid till 07-07-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	16,995.48	7%	1,242.88	17,755.48	18,998.36

Steve (LKK) wil Au
2/7/21, 10-09am
S djs
P/P
My Bel sy

Customer to Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

---VISIT OUR WEBSITE, aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions). ---
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Service Advisor