



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0547/2021/ZK
DATE : 2-Jul-21
WIP : 33154

Derise.
\$6285.30
04 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 02/07/2021

YOUR INSURED VEH NO : GBG 911 K

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR PRABURAM RAJAN
ADDRESS : 143 SERANGOON AVE 3
#14-01
SINGAPORE 556121
TELEPHONE : HP +65 91849073
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900247429
VEHICLE NO : SJW 4392 C
MODEL CODE : A4 SEDAN 2.0 TFSI
MODEL YEAR : 27/11/2019
ENGINE NO : CVK 087255
CHASSIS NO : WAUZZZF44KA113388
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Jun-21
PLACE OF ACCIDENT : NEWTON CIRCUS



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SJW 4392 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOP, HEADLIGHT WASHER ASSY & FRONT PARKING ATD	S/N \$ 480.00	?? ✓ <i>HS</i>
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X.
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	S/N \$ 2,100.00	1400 ✓
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1400 ✓
5	TO RENEW LHS FRONT RIMN AND CARRY OUT WHEEL ALIGNMENT	S/N \$ 280.00	240 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 5,402.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 4392 C

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Defend</i>	1	\$ 1,787.00	✓	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 587.00	+	
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 71.00	+	
4	FRONT BUMPER CLOSING ELEMENT - CLOSING ELEMENT <i>new</i>	1	\$ 210.00	+	
5	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 63.00	+	
6	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 135.00	+	
7	FRONT BUMPER GUIDE SECTION - LH <i>Not Nec</i>	1	\$ 36.00	×	
8	FRONT FENDER - LH <i>Dented</i>	1	\$ 767.00	✓	✓ 766.50
9	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 202.00	+	
10	FRONT FENDER CLOSING ELEMENT LH <i>Not Nec</i>	1	\$ 72.00	×	
11	FRONT FENDER BRACKET - LH <i>Not Nec</i>	1	\$ 35.00	×	
12	POP RIVET <i>new</i>	6	\$ 20.00	✓	19.80
13	FRONT FENDER BRACE- LH <i>Not Nec</i>	1	\$ 118.00	×	
14	FRONT FENDER BRACKET LH - UPPER CENTER <i>Not Nec</i>	1	\$ 49.00	×	
15	FRONT FENDER BRACKET LH - UPPER REAR <i>Not Nec</i>	1	\$ 32.00	×	
16	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 240.00	+	
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 233.00	+	
18	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$ 73.00	+	
19	FRONT FENDER LEDGE COVER - LH UPPER CENTER <i>Not Nec</i>	1	\$ 31.00	×	
20	FRONT FENDER LEDGE COVER - LH UPPER FRONT <i>Not Nec</i>	1	\$ 23.00	×	
SUB TOTAL SPARE PARTS		:	\$ 4,784.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 4392 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	LED HEADLIGHT - LH <i>new</i>	1	\$ 7,693.00	+	
22	STONE CHIP GUARD - LH <i>new</i>	1	\$ 51.00	+	
<i>polish</i> 23	FRONT ALUMINIUM RIM - LH new <i>new</i>	1	\$ 1,142.00	+	X
24	SUNDRIES <i>new</i>		\$ 300.00	+	X
TOTAL SPARE PARTS		:	\$ 13,970.00		
TOTAL LABOUR CHARGES		:	\$ 5,402.00		
GRAND TOTAL		:	\$ 19,372.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lin*
SURVEYED DATE : *08/07/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 24 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT