

NTUS-45
LKK-

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305475953
 REGN NO : SHC8562G
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 10.12.2015
 DATE/TIME IN : 29.06.2021 09:45
 ACCIDENT DATE : 29.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	de	
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	RK un	
0003 04-01-0103-0739-G	REAR BUMPER SPONGE	1	119.50	20.00	95.60	X un	
0004 04-01-0103-0740-G	REAR BUMPER BEAM	1	428.40	20.00	342.72	un	
0005 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	rel	1128 25% - 902.40
0006 04-01-0103-1150-A	REAR BUMPER MAT/PLATE	1	50.00		50.00	rel	50 122.13
0007 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	10.00	122.13	m	1074.53

SUB-TOTAL : 1,695.25

JOB NATURE

0000 PB	PANEL BEATING-SHC8562G	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	R/I REVERSE SENSORS	120.00	30
0003 20-05	Rear Bumper Adv.Sticker.	50.00	ad / 610

1074.53

610

1684.53

1/58 1350, 2 days