



Date : 03/08/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

Insured By : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
Nett Item			
1	HEADLAMP LH	3243.00	3243.00
1	HEADLAMP LOWER BRACKET RH	255.00	255.00
1	AIRCON CONDENSER	420.00	420.00
1	TURBO INTERCOOLER	1170.00	1170.00
1	RADIATOR TOP COVER	95.00	95.00
1	RADIATOR LOWER AIRGUIDE	156.00	156.00
1	AIRCON COOLING PIPE	204.75	204.75
1	AUTO OIL COOLER	645.00	645.00
1	ENGINE LOWER COVER	378.00	378.00
1	FRONT BUMPER	682.90	682.90
1	FRONT BUMPER LOWER GARNISH	195.20	195.20
10	FRONT BUMPER CLIPS	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	831.50	831.50
1	FRONT BUMPER BEAM	415.70	0.00

PAGE : 1

Date : 03/08/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

Insured By : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT BUMPER SPONGE	219.50	219.50
2	FRONT BUMPER REINFORCEMENT BRACKET	387.40	387.40
2	FRONT BUMPER LOWER ABSORBER	219.00	0.00
1	FRONT BUMPER RETAINER RH	25.40	25.40
1	FRONT GRILLE	486.00	486.00
10	FRONT GRILLE CLIPS	80.00	80.00
1	FRONT GRILLE LOGO	125.40	125.40
1	HEADLAMP RH	3243.00	3243.00
1	BONNET	1134.50	1134.50
10	BONNET INSULATOR CLIPS	100.00	0.00
2	BONNET HINGE RH/LH	130.00	130.00
1	BONNET LOCK	70.00	0.00
1	FRONT FENDER RH	753.50	0.00
1	FRONT FENDER INNERSHIELD RH	128.30	128.30
	RESTORE		

PAGE : 2



Date : 03/08/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

Insured By : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
10	FRONT FENDER SHIELD CLIPS	50.00	50.00
1	FRONT FENDER WHEELARC GARNISH RH	540.50	540.50
1	FRONT BUMPER SDIE GARNISH RH	125.50	125.50
1	FRONT FOGLAMP RH	301.00	0.00
1	HEADLAMP TOP PANEL RH RESTORE	83.90	0.00
1	SUPPORT TOP PANEL RESTORE	588.10	0.00
1	SUPPORT LOWER PANEL RESTORE	110.00	0.00
1	WIPER WASHER TANK	188.50	0.00
1	FRONT AIRGUIDE RH	90.20	90.20
Sub Total		16386.25	15092.05
Discount 10% On Parts		(0.00)	(1509.20)
Special Nett Item			
1	FRONT NUMBER PLATE	35.00	35.00
1	COOLANT	30.00	0.00

PAGE : 3



Date : 03/08/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

Insured By : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	65.00	35.00
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	1000.00	600.00
	TO RESPRAY AFFECTED AREAS	1000.00	700.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30.00
	TO TOP UP AIRCON GAS	120.00	100.00
	Sub Total	2170.00	1430.00

PAGE : 4



Date : 03/08/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

Insured By : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	18,364.57	15,047.84
	GST 7.0 %	1,285.52	1,053.35
	Total	19,650.	16,101.

Surveyor Name : TAUFIK - LKK

Date & Time : 05/07/2021 3:30:00 PM

Salamatshahh

PAGE : 5

CLAIM DEPARTMENT

DID : 66547519

FAX :

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 03/08/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
SUPPLEMENTARY

Attn : **Motor Claim Department**

FAX :

Owner : CHONG CHEE SENG, KLENN

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00

Accident Date : 25/06/2021

Vehicle No : SLV-5173-T

Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	HEADLAMP LH	3,243.00	cra
1	HEADLAMP LOWER BRACKET RH	255.00	de ✓
1	AIRCON CONDENSER	420.00	bt ✓
1	TURBO INTERCOOLER	1,170.00	bt
1	RADIATOR TOP COVER	95.00	de ✓
1	RADIATOR LOWER AIRGUIDE	156.00	de
1	AIRCON COOLING PIPE	204.75	bt ✓
1	AUTO OIL COOLER	645.00	bt
1	ENGINE LOWER COVER	378.00	de ✓

Date : 03/08/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
SUPPLEMENTARY

Attn : **Motor Claim Department**

FAX :

Owner : CHONG CHEE SENG, KLENN

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00

Accident Date : 25/06/2021

Vehicle No : SLV-5173-T

Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	6566.75	
	Discount 10% On Parts	(656.67)	

5,910.07

Remarks:

SUB TOTAL

GST 7.0 % 413.71

TOTAL 6,323.78

Surveyor's name: _____

Principal's name: CHONG CHEE SENG, KLENN

Survey Date & Time: _____