

Hui Zhen (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Thursday, 8 July 2021 2:11 pm
To: Hui Zhen (LKK Auto)
Subject: RE: PAPER SURVEY SMZ 1582P Surveyed by Taufikh

Dear Hui Zhen,

Audit check done for SMZ1582P, found undercarriage parts replaced without wheel alignment report.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)
Sent: Thursday, 8 July, 2021 1:10 PM
To: Simon Ho (LKKAuto)
Subject: PAPER SURVEY SMZ 1582P Surveyed by Taufikh

Dear Simon,

For your audit.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)