

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref: CS/MSG21007262/Uqf3		
4 SHENTON WAY #21-01,SGX CENTRE 2		Date: 02/07/2021		
SINGAPORE 068807		Code: MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBR 8383Z	Veh. Inspected	PC 3955U	
Policy No.	29145958AT2	Coverage (\$)	0.00	
Claim No.	636831	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	02/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/07/2021	Inspection Date	05/07/2021	
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				