

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197421559W (GST Reg. No M2-0020081-X)
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Bang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 58853
Date Estimated : 02/07/2021
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -
You Jianming
23 Sembawang Crescent
#12-07

SINGAPORE 757054

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS9998H	WBAJA12060BJ21248	31/05/2019	520i	16573

DESCRIPTION

Replace rear bumper include attachment etc and repair on rear boot lid
1/2

Painting rear boot lid and rear bumper

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To remove and install boot compartment carpet and garnish to facilitate repair.

To replace rear exhaust silencer including alignment system and conduct check for leak.

Sundries.

VALUE
1275 2,125.00
1972 2,076.00
168 177.00
168 177.00
257 271.00
X 531.00
150.00

Total Labour 1: 5,507.00

DESCRIPTION	QTY	PRIC	VALUE
CLAMPING BUSH	1	60.90	60.90
TAILPIPE TRIM BLACK CHROME D=80MM	2	159.20	318.40
REAR SILENCER	1	1,353.40	1,353.40
LEFT PROTECTION FOIL	1	13.50	13.50
RIGHT PROTEC	1	13.50	13.50
REAR BUMPER CARRIER	1	582.55	582.55
REAR BUMPER BOTTOM REINFORCEMENT	1	75.90	75.90
REAR BUMPER CENTRE GUIDE	1	67.80	67.80
REAR BUMPER TRIM STRIP	1	116.60	116.60
REAR BUMPER TOWING EYE FLAP PRIMED	1	52.90	52.90
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,627.25	1,627.25
SET MOUNTING PMA SENSOR	1	69.70	69.70
EMBLEM GROMMET	2	0.85	1.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (After Sales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 58853
Date Estimated : 02/07/2021
Prepared By : Chua Kee Sin

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS9998H	WBAJA12060BJ21248	31/05/2019	5201	16573

DESCRIPTION	QTY	PRIC	VALUE
LETTERING 5201 / ncc	1	64.75	64.75
PLAQUE 74MM / ncc	1	71.95	71.95
REAR SILENCER LH HEAT INSULATION / n X nn	1	98.90	98.90
REAR LH LIGHT IN THE SIDE PANEL / CUT	1	641.15	641.15
REAR LH LIGHT IN TRUNK LID / CUT	1	378.70	378.70
LH TAIL LIGHT FINISHER TRUNK LID / n X nn	1	35.15	35.15
ULTRASONIC SENSOR BLACK / n X nn	4	251.20	1,004.80
DECOUPLING RING PDC TORQUE CONVERTER / ncc X nn	4	5.15	20.60
Total Parts :			6,670.10

Steve CLKK)
9/7/21, 1239cn

WIL PL
65 d/s
P/P

M Bel Sy

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time _____	Excess S\$ _____
Surveyor's Name _____	Sign _____
Surveyor's Tel _____	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend _____	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12,218.30

Labour 1	:	5,507.00
Parts	:	6,670.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	852.40
Grand Total	:	13,029.50

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

