


MBM WHEELPOWER PTE LTD

Your Ref: EV36Y
Our Ref: SMQ9585B



To: MSIG

CC

Fax

Date: 21/7/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA ALPHARD 2.5
Chassis No.: AGH300246845
Engine No.: 2ARJ279933
Year of Make: 2019
Accident Date: 1 July 2021

ESTSUPPLEMENTARY FOR VEHICLE NO. : SMQ9585B

DESCRIPTION

FRONT RH FENDER BRACKET bent

QTY		List Price
1	\$	75.00
Total:	\$	75.00
LESS 25%	\$	(18.75)
Parts Total:	\$	56.25

LABOUR


TO SPRAY PAINT ON THE AFFECTED AREAS

30	\$	150.00
Total:	\$	206.25
7% GST:	\$	14.44
Grand Total:	\$	220.69

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62628888 f 64525333

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD



Your Ref: EV36Y
Our Ref: SMQ9585B

*Not Notified
Running By pain
5 days*

To: MSIG

CC

Fax

Date: 2/7/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA ALPHARD 2.5
Chassis No.: AGH300246845
Engine No.: 2ARJ279933
Year of Make: 2019
Accident Date: 1 July 2021

ESTIMATE FOR VEHICLE NO.: SMQ9585B

DESCRIPTION

FRONT BUMPER
FRONT BUMPER RH SIDE RETAINER
FRONT BUMPER RH CHROME
HEAD LAMP RH
HEAD LAMP RH CHROME
FRONT RH FENDER
BUMPER CLIPS

QTY	List Price	
1	\$ 2,250.00	?
1	\$ 95.00	Dr 1 ✓
1	\$ 210.00	CM ✓
1	\$ 4,050.00	mgent ✓
1	\$ 210.00	mgent ✓
1	\$ 680.00	Bu ✓
10	\$ 60.00	?
Total:	\$ 7,555.00	
LESS 25%	\$ (1,888.75)	
Parts Total:	\$ 5,666.25	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO APPLY ANTI RUST COATING
TO REMOVE & REPLACE BUMPER SENSORS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO SPRAY PAINT ON THE AFFECTED AREAS

	\$ 1,000.00	4001
	\$ 300.00	?
	\$ 150.00	301
	\$ 60.00	?
	\$ 80.00	201
	\$ 1,000.00	6601
Total:	\$ 8,256.25	
7% GST:	\$ 577.94	
Grand Total:	\$ 8,834.19	

Parts: \$3978.75

L: \$1410

S: \$206.25

Total: \$5595.15

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62628888 f 64525333

Company Registration Number : 200204110W