

# **\*AIR ESTIMATE\***

VEHICLE NO    **SHA2205M**

DATE

MAKE

**01/07/21**

MODEL

**: HYUNDAI IONIQ G3**

**CHIANG /AIG**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			<del>RX</del> \$430.90
1	FRONT BUMPER CENTRE MOULDING			nn X \$368.50
1	FROBT BUMPER BRACKET LH			nn R \$35.00
1	FRONT FENDER LH			RP \$588.80
1	FRONT FENDER EMBLEM LH			<del>ARC</del> X \$26.20 Xnn
	<b>SUB TOTAL</b>			<b>\$1,449.40</b>
	<b>20.00%</b>			<b>\$299.88</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,159.52</b>
	<b>Labour Charge</b>			
	Panel Beating			350 \$550.00
	Spray Paint			500 \$600.00
	Reset front wheel alignment			X \$60.00 nn
	Check lighting			X \$60.00 nn
	<b>TOTAL LABOUR</b>			<b>\$1,270.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,429.52</b>
<p><i>Tanpin 97P15749</i>  <i>WP 5/7/21 C 430</i>  <i>P/P Resurvey before paint</i>  <i>Tanpin C/Khandon</i>  <i>2 days</i></p> <p><i>\$ 850 #</i>  <i>2 days.</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: