



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref:	CS/LAW21007313/Uqf3e2
TOKIO MARINE INSURANS (M) BHD C/O : TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02 GUOCO TOWER SINGAPORE 078881			Date:	23/07/2021
			Code:	LAW
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	JEG 6200	Veh. Inspected	SLP 4487B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CF.SKS.so.1010.20-tm(m)	Excess (\$)	0.00
	Assign From	STELLA OW	Assign Date	03/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8H0152961	Colour	GREY
	Odometer	255286 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TRIANGLE	6 mm
	L/H Front Tyre	205/60 R16	TRIANGLE	6 mm
	R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
	L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
	REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	06/03/2020	Inspection Date	07/07/2021
	Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 74 Kian Teck Road Singapore 628800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	