

ASS. BY:

REF:

CS/FCI21007322/D983

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. **D21000924MFSH**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: **16** days Res.: Yes or NoLump Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SKW 6026 K** Yr Regn: **Nov / 2015**Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Porsche Macan** C.C. **1984**Colour: **Blue** A/C: Insured / Std / NI / NASp. Reading: **60598** T/Radio: Insured / Std / NI / NAEng/No: **139290**C/No: **WP122295ZGL-B05649**Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **235/60 R18**R: **— 11 —**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Michelin**

Front Rear

R/Bal. **S** mm R/Bal. **S** mmL/Bal. **S** mm L/Bal. **S** mmD.O.A. **23/03/2021** D.O.I. **08/07/2021**Survey held at **JW G AMK**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

**Physical Re-inspection****MV 160K****VIA 89.9K****HL 70.1K****Repair incident parts themselves from overseas.****16/07/2021 Submit 4555000/- with 16 days for**

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/07 Typist

☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: **16**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

Report Format: **TR**Lump Sum / Total: **55000**



SMRT Automotive Services Pte Ltd

Our Ref No :

SR/03/21/0008

**Automobile Inspection Report****1) REFERENCE**

Policy No : NA Date Of Accident : 23/03/2021 1555pm  
Claims No :                      Date Of Inspection : 25/03/2021 1530pm  
Assigned by : Hua Yen 25/03/2021 1111am Date Of Re-Inspection : AF repair photo send 17/06/21 1549pm  
Case Ref No : TAX/03/21/2074 Inspected By : Low Thian Seng

**2) VEHICLE PARTICULARS**

Veh Reg No : SKW6026K Engine No : 139290  
Make / Model : Porsche Macan 2.0 A/T Chassis No. : WP1ZZZ95ZGLB05649  
Year : 11/06/2015 Mileage : 59594  
Colour : Blue

**3) CONDITION OF VEHICLE ( Static Check )**

Foot brake : Serviceable Handbrake : Serviceable  
Steering : Serviceable Paintwork : Good

**4) TYRE CONDITION**

	Size	Make	Balance
Frt Right	<u>235 60R 18</u>	<u>Michelin</u>	<u>7mm</u>
Frt Left	<u>235 60R 18</u>	<u>Michelin</u>	<u>7mm</u>
Rear Right	<u>235 60R 18</u>	<u>Michelin</u>	<u>7mm</u>
Rear Left	<u>235 60R 18</u>	<u>Michelin</u>	<u>7mm</u>

**5) DESCRIPTION OF DAMAGES**

The vehicle sustained damage at the front Portion.  
For details, please refer to photographs and assessment for repairs.

**6) INSPECTION**SURVEY HELD AT : C.S Ong Auto Pte Ltd / AMK Autopoint #02-16PHOTOGRAPH TAKEN : 111 INSPECTION ON : 25/03/2021 1530pm

**REMARKS :** ( SUBJECT TO POLICY CONDITION )  
WITHOUT PREJUDICE

ESTIMATED NORMAL PERIOD FOR REPAIRS : 19 days  
IN ACCORDANCE TO YOUR INSTRUCTION , WE HAVE NOT AUTHORISED REPAIRS .

This estimate covers visible damages only . Should there be any discrepancy or unseen items in this survey , kindly notify the company within ( 7 ) days from the date hereof . Otherwise this estimate / acceptance shall be treated as valid .

\* Remarks : SMRT Taxi - SHB834E

Xin Ming Ong - 64841933

Lump Sum Repair



Vehicle No : SKW6026K

Policy No :

NA

Claim No :

Our Ref No

SR/03/21/0008

**ADJUSTMENT ON REPAIRS COST AND REPLACEMENT OF PARTS**

Qty	Descriptions of parts	Condition	Repairers Est (\$)	Recommendation Revised (\$)	
1	Frt Windscreen	Cracked	\$3,492.00	\$3,492.00	✓
1	Frt Windscreen Moulding	Necessary	\$429.00	\$429.00	✓
1	Frt Wiper Lower Garnish	Deformed	\$611.00	\$611.00	✓
2	Frt Wiper Side Garnish LH/RH	Damage / LH	\$858.00	\$429.00	✓
1	A Pillar LH	Dented	\$2,490.00	\$2,490.00	R
2	Frt Door LH / RH	Repair	\$6,208.00	-	HN
1	Side Mirror Assy LH	Cracked	\$2,182.00	\$2,182.00	R
1	Bonnet	Buckled	\$5,170.00	\$5,170.00	✓
1	Bonnet Seal	Serviceable	\$200.00	-	SV
1	Bonnet Insulator	Torn	\$998.00	\$998.00	✓
2	Bonnet Hinge LH/RH	Bent	\$621.00	\$621.00	✓
2	Bonnet Damper LH/RH	Bent	\$2,180.00	\$2,180.00	✓
2	Bonnet Lock LH/RH	Bent	\$1,318.00	\$1,318.00	✓
2	Bonnet Striker Lock LH/RH	Bent	\$278.00	\$278.00	✓
1	Bonnet Logo	Necessary	\$210.00	\$210.00	✓
2	Head Lamp LH/RH	Cut / Cracked	\$13,442.00	\$13,442.00	✓
2	Head Lamp Lower Bracket LH/RH	Damage / LH	\$638.00	\$319.00	✓
2	Head Lamp Rubber Garnish LH/RH	Torn	\$588.00	\$588.00	✓
2	Head Lamp Lower Garnish LH/RH	Damage / LH	\$796.00	\$398.00	✓
2	Head Lamp ECU LH/RH	Damage / LH	\$6,280.00	\$3,140.00	✓
1	Head Lamp Wire Harness Complete	Torn / Cut	\$4,210.00	\$4,210.00	HN
1	Frt Grille	Cut	\$1,005.00	\$1,005.00	✓
1	Frt Bumper	Broken	\$2,980.00	\$2,980.00	✓
2	Frt Bumper Side Retainer LH/RH	Damage	\$478.00	\$239.00	✓
2	Frt Bumper Signal Lamp LH/RH	Cut	\$1,564.00	\$1,564.00	✓
2	Frt Bumper Signal Lamp Garnish LH/RH	Damage / LH	\$882.00	\$441.00	✓
2	Frt Bumper Fog Lamp LH/RH	Serviceable	\$1,318.00	-	HN
2	Frt Bumper Fog Lamp Garnish LH/RH	Damage / LH	\$802.00	\$401.00	HN
2	Frt Bumper Fog Lamp Holder LH/RH	Damage / LH	\$796.00	\$398.00	HN
1	Frt Bumper Lower Grille	Serviceable	\$1,071.00	-	HN
1	Frt Bumper Under Cover	Bent	\$799.00	\$799.00	HN
4	Frt Bumper Sensor	Multifunction / 2pcs	\$2,040.00	\$1,020.00	✓
4	Frt Bumper Sensor Holder	Damage / 3 pcs	\$80.00	\$60.00	✓
1	Frt Bumper Sensor Wire Harness	Serviceable	\$2,680.00	-	HN
1	Frt Bumper Sponge	Cracked	\$690.00	\$690.00	✓
1	Frt Reinforcement Bar	Serviceable	\$2,741.00	-	HN
1	Frt Support Panel	Damage	\$3,189.00	\$3,189.00	✓
1	Frt Support Panel Top Garnish	Cracked	\$710.00	\$710.00	✓
1	Frt Inter Cooler Assy	Serviceable	\$3,149.00	-	
1	A/C Condensor	Serviceable	\$2,840.00	-	
1	A/C Condensor Suction House	Serviceable	\$1,194.00	-	
1	A/C Condensor Discharge House	Serviceable	\$1,295.00	-	
1	A/C Condensor Fan Complete	Serviceable	\$1,519.00	-	
1	Radiator Assy	Serviceable	\$3,004.00	-	
1	Radiator Fan Motor	Serviceable	\$892.00	-	
1	Radiator Fan Blade	Serviceable	\$590.00	-	
1	Radiator Fan Cowling	Serviceable	\$887.00	-	
1	ABS Pump Assy Complete	Damage	\$12,900.00	\$12,900.00	HN
2	Frt Fender LH / RH	Damage / LH	\$3,364.00	\$1,682.00	✓
2	Frt Fender Inner Shield LH / RH	Cut / LH	\$820.00	\$410.00	✓
2	Frt Fender Top Garnish LH / RH	Cut / LH	\$942.00	\$471.00	✓
2	Frt Fender Top Garnish Styrofoam LH / RH	Damage / LH	\$240.00	\$120.00	✓
2	Frt Rim LH / RH	Cut / Bent	\$6,360.00	\$6,360.00	✓
2	Frt Wheel Bearing LH / RH	Necessary	\$1,198.00	\$1,198.00	✓

446005.00



2	Frt Wheel Bearing Hub LH / RH	Bent	\$1,380.00	\$1,380.00	✓
2	Frt Knuckle Arm LH / RH	Bent	\$3,780.00	\$3,780.00	✓
2	Frt Lower Arm LH / RH	Bent	\$2,180.00	\$2,180.00	✓
2	Frt Thrust Arm LH / RH	Bent	\$1,858.00	\$1,858.00	✓
2	Frt Upper Arm LH / RH	Bent / LH	\$2,442.00	\$1,221.00	✓
4	Frt Upper Arm Linkage LH / RH	Bent / LH	\$1,220.00	\$610.00	✓
2	Frt Absorber LH / RH	Bent	\$7,620.00	\$7,620.00	✓
2	Frt Stabilizer Linkage LH / RH	Bent / LH	\$984.00	\$492.00	✓
1	Frt Stabilizer Bar	Serviceable	\$888.20	--	✓
1	Steering Rack & Pinion Assy	Serviceable	\$5,020.00	--	✓
2	Drive Shaft LH / RH	Serviceable	\$9,004.00	--	✓
			\$154,594.20	\$98,283.00	
			Less 10%	\$15,459.42	\$9,828.30
			<b>\$139,134.78</b>	<b>\$88,454.70</b>	

18649-w  
73335-w  
66001-50

#### Net Items

Qty	Descriptions	Condition	Repairers Est (\$)	Recommendation Revised (\$)
1	To Supply Frt Bumper Clips	Necessary	\$80.00	\$40.00 20/-
1	To Supply Frt Grille Clips	Necessary	\$80.00	\$40.00 15/-
1	To Supply Signal Lamp Garnish Clips	Necessary	\$80.00	\$40.00 15/-
1	To Supply Fog Lamp Garnish Clips	Necessary	\$80.00	\$40.00 15/-
1	To Supply Frt Bumper Lower Grille Clips	Necessary	\$80.00	\$40.00 15/-
1	To supply Frt Bumper Under Cover Clips	Necessary	\$80.00	\$40.00 15/-
1	To supply Frt Fender Inner Shield Clips	Necessary	\$80.00	\$40.00 15/-
1	To Supply Wiper Garnish Clips	Necessary	\$80.00	\$40.00 15/-
1	To Supply Support Panel Top Garnish Clips	Necessary	\$80.00	\$40.00 15/-
1	To Supply Frt Windscreen Sealant	Necessary	\$120.00	\$80.00 40/-
1	To supply Frt Windscreen Damping Seal	Necessary	\$50.00	\$30.00 15/-
1	To Supply Frt Windscreen Inner Seal	Necessary	\$80.00	\$50.00 15/-
1	To Supply Frt Windscreen Solar Film	Necessary	\$800.00	\$500.00 40/-
2	To Supply Tyre	Serviceable	\$2,000.00	--
1	To Supply Coolant	Necessary	\$300.00	\$100.00 15/-
			<b>\$4,070.00</b>	<b>\$1,120.00</b>

135-w

#### Our Charges & Misc

Remove interior upholstery items to facilitate repairs	\$300.00	\$120.00 40/-
Knock out dents and replace accident part	\$4,000.00	\$2,500.00 1400/-
Putty and spray painting on accident affected portion	\$4,000.00	\$1,400.00 1000/-
Buff coat damaged areas	\$300.00	\$100.00 40/-
RNR inter-cooler to facilitate repairs	\$200.00	--
RNR A/C condensor & refill gas to facilitate repairs	\$200.00	\$80.00 15/-
RNR radiator & refill coolant to facilitate repairs	\$200.00	\$60.00 50/-
RNR frt undercarriage to facilitate repairs	\$800.00	\$400.00 300/-
Conduct computerized wheel alignment	\$120.00	\$80.00 60/-
RNR frt door mechanism to facilitate repairs	\$250.00	--
RNR frt windscreen to facilitate repairs	\$500.00	\$200.00 120/-
check & re-fix all electrical wirings	\$200.00	\$80.00 30/-
computerize diagnose fault codes & control units, reset all memories default settings	\$3,000.00	\$300.00 150/-
		<b>\$14,070.00</b>
		<b>\$5,320.00</b>
		<b>\$157,274.78</b>
		<b>\$94,894.70</b>
		<b>\$75,900.00</b>

3230-w

Grand Total :  
Lump Sum

#### JUSTMENT / RECOMMENDATIONS

No of days repair : 19 days

We have thoroughly inspected each and every item on the estimate against the physical damage found the vehicle we have noted the breakdown of our findings and our recommendation as per assessment above.

Automotive Services Pte Ltd  
W Thian Seng  
Fax No : 63687421  
Tel No : 68662796  
Email : thianseng@smrt.com.sg

16 days

69366-50  
1/5 55000/-

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	297G
<b>Vehicle Details</b>	
Vehicle No.:	SKW6026K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Mar 2021
Vehicle Make:	PORSCHE
Vehicle Model:	MACAN 2.0 A/T ABS D/AIRBAG AWD S/R
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	139290
Chassis No.:	WP1ZZZ95ZGLB05649
Maximum Power Output:	174.0 kW (233 bhp)
Open Market Value:	\$65,640.00
Original Registration Date:	06 Nov 2015
First Registration Date:	06 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$90,152.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Nov 2025
PARF Rebate Amount:	\$63,106.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	05 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$26,876.00
<b>Total Rebate Amount:</b>	<b>\$89,982.00</b>

The information contained herein is correct as at 23 Mar 2021

OK





## BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

### START SEARCH NOW!

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Approval Case Up To 99%, High Trade-In.



1.88% Interest Rate For Bank  
Loan & 3.28% In House  
Financing 100% Loan.  
5G Motors StarAd



view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

porsche macan 2.0

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>porsche macan 2.0</b>		Any	Any	<b>2016</b>	Any	Any	Any	<b>Available</b>
	Porsche	Macan 2.0A PDK	\$173,888	\$25,710 /yr	25-Apr-2016	1,984 cc	48,500 km	SUV	Available
Serviced & Oil Changed In March 2021, Brand New Brake Pads, Brand New Golden White Car Wrap, Genuine Low Mileage, Agent Unit, Fully Agent Services, Recently Has Done A Pre Warranty Extension Checks And Is Approved For Warranty Extension, Elegant Hold Exteri...									
Euro Performance Asia Pte Ltd									
Posted: 25-Mar-2021 Tags: 2016 Porsche Macan, Porsche Macan, Porsche, Macan									
	Porsche	Macan 2.0A PDK	\$175,800	\$26,660 /yr	19-Feb-2016	1,984 cc	72,000 km	SUV	Available
The Stylish Porsche Macan Is Poised To Set New Standards In The Field Of Driving Dynamics And Enjoyment In The Compact SUV Segment. Vast Engine Power, Extreme Agility And Optimum Steering Precision With High Level Of Comfort And Suitability.1 Meticulous L...									
Posted: 23-Mar-2021 Tags: 2016 Porsche Macan, Porsche Macan, Porsche, Macan									

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used porsche macan 2.0, porsche macan 2.0 Singapore, used porsche macan 2.0 Singapore, used porsche macan 2.0, used vehicles Singapore or even buy used porsche macan 2.0 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com