

VOLKSWAGEN CENTRE SINGAPORE
247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
CORDELIA
LEE
261 RIVER VALLEY ROAD
#10-28
Singapore 238307

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

02-07-2021
5211001170
200208384E
30001
2021024705/ 1
02-07-2021
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SDK7201K	7N14H3	30-11-2012	WVWZZZ7NZDV012310	Sharan succ. HL 147 TSID6F	61,175

Repair limit:

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
7N0831056AF	Door RHF <i>bt</i>	1	pcs.	2,281.09	#1	2,281.09	2,440.77
7N0837701C	Door Seal Outer RHF <i>3na</i>	1	pcs.	361.35	#1	361.35	386.64
D 378500A2	Sound Absorber Laminated RHF <i>3na</i>	1	pcs.	43.65	#1	43.65	46.71
7N0821022B	Fender RHF <i>3repair</i>	1	pcs.	807.29	#1	807.29	863.80
7N0821136A	Cross Support RHF FENDER BRACKET <i>3Xsuc</i>	1	pcs.	49.27	#1	49.27	52.72
D 314D36M2	Long-Life Underseal <i>X n</i>	1	pcs.	87.64	#1	87.64	93.77
7N2857508AC9B9	Rear View Mirror Housing RH <i>3X not consistent xnn</i>	1	pcs.	815.87	#1	815.87	872.98
5N0857538 GRU	Mirror Cap Primed RH <i>3X not consistent xnn</i>	1	pcs.	137.26	#1	137.26	146.87
5N0857522C	Mirror Glass RH <i>3X not consistent xnn</i>	1	pcs.	207.82	#1	207.82	222.37
	LABOUR	4	pcs.	840.00	#1 <i>1680</i>	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1 <i>1600</i>	3,200.00	3,424.00
	Spray Painting Wing Cover	1	pcs.	280.00	#1 <i>na</i>	280.00	299.60
CHINA TAIPING DIRECT SETTLEMENT DOA: 2/7/2021 TP VEH: SJW2861D SURVEY BY:							

Quotation valid till 09-07-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	11,631.24	7%	867.39	12,391.24	13,258.63
Total	760.00	11,631.24		867.39	12,391.24	13,258.63

Customer

Service Advisor

ASUC
HP 90010060
4 days
07/07/21 @ 14/10

Resurvey before print

Survey Fee:

Days Of Repair: