



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21007350/Uuf3n2	
			Date: 01/10/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GX 2223B	Veh. Inspected	SMA 8721R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102005/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	06/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FREED HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GB71067509	Colour	BLACK
	Odometer	38387 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	8 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	8 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	8 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/07/2021	Inspection Date	15/07/2021
	Survey held at	15 FAN YONG ROAD SINGAPORE 629792		
	Repairer	MOVA AUTOMOTIVE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	