



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 05/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8805R	0	63187	73/DS/SLP8805R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3302009857		2NRX145549	60	Ary Chua	06/07/2021 8.00		13/07/2021 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: 04/07/2021@15.5 4PMACC DATE:02-07-2021@19.45PM DRIVE IN:05-07-2021@15.00PM EXCESS: DATE SURVEY: NO OF REPAIR DAYS: 5 DAY TP VEH: SHF178U TAXI						50.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME			BP08			180.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR END PANEL AND REAR BOOTLID						100.00
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.			BP45			122.40
5	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.			BP45			180.00
6	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.			*			2880.00
7	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.			*			1770.00
8	1	K81550-0D550 LAMP ASSY, RR COMBIN			1.00	323.00		323.00
9	2	K81560-0D550 LAMP ASSY, RR COMBIN			1.00	323.00		323.00
10	3	K52159-0U908 COVER, RR BUMPER, L			1.00	526.00		526.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts		Less	Amount Due
					Labour			
					Sublet			
					Lubrication/Fluid			
					Others			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 05/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8805R	0	63187	73/DS/SLP8805R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3302009857		2NRX145549	60	Ary Chua	06/07/2021 8.00		13/07/2021 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
11	4	K52161-0K040 PIECE, RR BUMPER			4.00	4.10		16.40
12	5	K52023-0D100 REINFORCEMENT SUB-AS			1.00	336.30		336.30
13	6	K58307-0D250 PANEL SUB-ASSY, BODY			1.00	722.50		722.50
14	7	T90467-08186 C3 CLIP			2.00	2.50		5.00
15	8	K64401-0D160 PANEL SUB-ASSY, LUGG			1.00	798.90		798.90
16	9	K64461-0D130 WEATHERSTRIP, LUGGAG			1.00	177.60		177.60
17	0	K75442-0D250 PLATE, LUGGAGE COMPT			1.00	46.00		46.00
18	1	K90975-T2006 EMBLEM, SYMBOL			1.00	53.70		53.70
19	2	K75444-0D460 PLATE, LUGGAGE COMPT			1.00	35.90		35.90
20	3	SPZ061-0D035 24 1G3 REVERSE SENSOR GREY METALLIC			1.00	146.70		146.70
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 8,793.40	
					Parts 3,511.00		GST 7.00% 615.54	
					Labour 5,282.40			
					Sublet 0.00		Less 0.00	
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 9,408.94	

Customer Copy