



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			05/07/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8805R	0	63187	73/DS/SLP8805R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFB29F3302009857	2NRX145549	60	Ary Chua	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: 04/07/2021@15.5 4PMACC DATE:02-07-2021@19.45PM DRIVE IN:05-07-2021@15.00PM EXCESS: DATE SURVEY: NO OF REPAIR DAYS: 5 DAY TP VEH: SHF178U TAXI				50.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR END PANEL AND REAR BOOTLID				120.00
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40
5	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				180.00
6	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR CAMERA AND OTHER ATTACHMENT TO FACILIATE REPAIRS				360.00
7	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				4320.00
8	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				3540.00
9	1	SPZ061-0D035 24 BACK SENSOR GREY METALLIC	1.00	146.70		146.70

For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							
		Please acknowledge receipt of vehicle		Parts			
				Labour			
				Sublet			
				Lubrication/Fluid			
				Others			
						Amount Due	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 05/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8805R	0	63187	73/DS/SLP8805R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3302009857		2NRX145549	60	Ary Chua	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
10	2	K81550-0D550 LAMP ASSY, RR COMBIN			1.00	323.00		323.00
11	3	K81560-0D550 LAMP ASSY, RR COMBIN			1.00	323.00		323.00
12	4	K81580-0D190 LAMP ASSY, RR, RH			1.00	191.30		191.30
13	5	K81590-0D150 LAMP ASSY, RR, LH			1.00	191.30		191.30
14	6	K52159-0U908 COVER, RR BUMPER, L			1.00	526.00		526.00
15	7	K52161-0K040 PIECE, RR BUMPER			4.00	4.10		16.40
16	8	K52575-0D240 RETAINER, RR BUMPER			1.00	121.30		121.30
17	9	K52576-0D240 RETAINER, RR BUMPER			1.00	121.30		121.30
18	0	K52023-0D100 REINFORCEMENT SUB-AS			1.00	336.30		336.30
19	1	K58307-0D250 PANEL SUB-ASSY, BODY			1.00	722.50		722.50
20	2	K58387-0D160 PLATE, RR FLOOR FINI			1.00	244.30		244.30
21	3	K90467-08186 C3 CLIP			2.00	2.50		5.00
22	4	K64401-0D160 PANEL SUB-ASSY, LUGG			1.00	798.90		798.90
23	5	K64461-0D130 WEATHERSTRIP, LUGGAG			1.00	177.60		177.60
24	6	K64610-0D080 LOCK ASSY, LUGGAGE C			1.00	95.00		95.00
25	7	K75442-0D250 PLATE, LUGGAGE COMPT			1.00	46.00		46.00
26	8	K90975-T2006 EMBLEM, SYMBOL			1.00	53.70		53.70
27	9	K75444-0D460 PLATE, LUGGAGE COMPT			1.00	35.90		35.90
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						13,347.90		
		Please acknowledge receipt of vehicle		Parts 4,475.50		GST 7.00% 934.35		
				Labour 8,872.40				
				Sublet 0.00		Less 0.00		
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due 14,282.25		

Company Copy