



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		NAME : ADDRESS : TEL :		WIP : 37225 EXCESS : DATE: 6-Jul-21	
ATTN : MOTOR CLAIMS FAX :		DATE IN :		CONTACT PERSON : JESS	
VEH NO :	SMN2119B	MILEAGE :		TYPE OF CLAIM : THIRD PARTY CLAIM	
CHASSIS NO :	JM6GL1072K0313005	DATE REG : 29-Jul-19		POLICY NO. :	
MODEL :	M6				

NATURE OF WORKS

Parts Description									
NO	DESCRIPTION	PARTS NO	QTY	/UNIT	DISC	1st	Supp	REVISED	PRICES
1	HEADLAMP RH / CUT	MGSK4-51-031A	1	4,759.30	20%	/			4,759.30
2	TAPE SEAL HEADLAMP RH / N/C	MGRF5-51-065A	1	102.00	20%	/			102.00
3	RIVET / N/C	MB092-51-833	1	3.50	20%	/			3.50
4	BRACKET 'A' HEADLAMP RH X nn	MGS7-50-ABXA	1	30.80	20%				30.80
5	BRACKET 'B' HEADLAMP RH X nn	MGS7-50-ABYA	1	15.50	20%				15.50
6	SIDE MIRROR RH / CR	MGSB9-69-121A	1	475.90	20%	/			475.90
7	HOUSING SIDE MIRROR RH / CUT	MB63B-69-1N1 13	1	111.00	20%	/			111.00
8	SIGNAL TURN LAMP RH / X nn	MB63B-69-122A	1	85.80	20%				85.80
9	GLASS & HOLDER RH / X nn	MB63C-69-1G1	1	282.50	20%				282.50
10	FRONT FENDER RH / N/C	MGHP9-52-111A	1	383.70	20%	/			383.70
11	FASTENER / N/C	MB45A-56-146A	10	3.00	20%	/			30.00
12	FRT BUMPER X R	MGSJ8-50-031 BB	1	1,211.90	20%				1,211.90
13	GROMMET, SCREW / N/C	MGHP9-50-025	1	2.90	20%	/			2.90
14	CHROME COVER FOG LAMP X nn	MBVG-50-121	1	65.80	20%				65.80
15	COVER FOG LAMP X nn	MGS7-50-101	1	20.50	20%				20.50
16	RETAINER RH FRONT BUMPER X nn	MGHP9-50-0T1B	1	17.10	20%				17.10
17	RIVET / N/C	MBBM4-50-355	4	4.50	20%	/			18.00
18	RIVET, SPLASH SHIELD X nn	MS51S-51-833	4	4.00	20%				16.00
19	CHROME MOULD OUTER FRONT DDOR RH X	MGHP9-50-640F / N/C	1	96.00	20%	/			96.00
20	FASTENER X nn	MGJ6A-68-AB1	9	7.20	20%				64.80
TOTAL PARTS									7,793.00
LESS 20%									1,558.60
TOTAL PARTS COST									6,234.40

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							-
TOTAL PARTS COST							-

Labour Description			
1		TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.	1,650.00
2		TO RESPRAY FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENTS.	2,520.00
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.	330.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.00
5	MZ-BR-REPRO	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.00
6	MZ-BR-SUNDR	SUNDRIES.	50.00

TOTAL LABOUR	-	4,880.00
TOTAL PARTS	-	6,234.40
TOTAL	-	11,114.40
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

SUPPLEMENTARY LABOUR DESCRIPTION			
1		#N/A	
2		#N/A	

TOTAL LABOUR	-	-
TOTAL PARTS	-	-
TOTAL	-	-
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

RANS EUROKARS PTE LT

Authorised Signature

Stere (LKK) wll h
12/7/21, 11.30am
8322 8813
4 yrs
P/P
My Bul sy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: