

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0544/2021/TF
DATE : 2-Jul-21
WIP : 33779

Celia
~~\$ 3693.44~~
6715.44

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 2/7/2021

YOUR INSURED VEH NO : SKT 6001 Y

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. TAN BOON KWONG
ADDRESS : BLK 568 HOUGANG ST 51
#16-77
SINGAPORE 530568
TELEPHONE : HP +65 96162556
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5112727728-01
VEHICLE NO : **SMK 9843 M**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 27/1/2016
ENGINE NO : CZD 218487
CHASSIS NO : WAUZZZ8U4GR045910
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Jul-21
PLACE OF ACCIDENT : CTE SOYTHBOND TOWARDS CITY, NEAR ANG MO KIO AVE 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 9843 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	✓
3	TO RESPRAY REAR BUMPER, REAR LOWER SPOILER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3,800.00	✓
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00	✗
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,952.00	

2050
3 x 550 = 1650
Arch Trim = 400
2050

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9843 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dehd</i>	1	\$ 1,580.00	✓ 1264.00
2	REAR BUMPER FIXING PARTS <i>ne n</i>	1	\$ 124.00	✗
3	REAR BUMPER SPOILER <i>Dehd</i>	1	\$ 880.00	✓ 704.00
4	REAR BUMPER DIFFUSER	1	\$ 706.00	✓ 564.40
5	TOWING EYE COVER - LH <i>Dehd</i>	1	\$ 43.00	✓ 34.08
6	TOWING EYE COVER - RH <i>Ne n</i>	1	\$ 26.00	✗
7	REAR BUMPER TAIL LIGHT - LH <i>Ne n</i>	1	\$ 457.00	✗
8	REAR BUMPER TAIL LIGHT - RH	1	\$ 457.00	✗
9	REAR BUMPER CARRIER <i>Ne Nec</i>	1	\$ 651.00	✗
10	HEX COLLARD BOLT <i>Ne Nec</i>	6	\$ 30.00	✗
11	REAR BUMPER SENSOR <i>Ne n</i>	2	TBC	✗
12	REAR BUMPER SEAL RING	4	\$ 6.00	✗
13	PACKING ADHESIVE <i>Ne</i>	1	\$ 19.00	✓ 14.88
14	AUDI EMBLEM <i>Ne</i>	1	\$ 138.00	✓ 110.00
15	Q3 EMBLEM	1	\$ 99.00	✓ 79.04
16	TFSI EMBLEM	1	\$ 99.00	✓ 79.04
17	REAR WHEEL ARCH - LH / RH <i>Ne</i>	2	\$ 1,056.00	✓ 844.00
18	REAR SILENCER <i>Ne n</i>	1	\$ 1,088.00	✗
19	REAR SILENCER DUAL CLIP <i>ne n</i>	1	\$ 59.00	✗
20	REAR SILENCER RETAINING CLIP CENTRE <i>Ne n</i>	1	\$ 17.00	✗
SUB TOTAL SPARE PARTS		:	\$ 7,535.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9843 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR SILENCER RETAINING CLIP - RH	1	\$ 17.00	+
22	REAR SILENCER RETAINING BRACKET - LH	1	\$ 73.00	+
23	TRIM SET EXHAUST TAILPIPES	1	TBC	✓
24	SUNDRIES <i>Not Nee.</i>	1	\$ 300.00	✗
TOTAL SPARE PARTS		:	\$ 7,925.00	
TOTAL LABOUR CHARGES		:	\$ 5,952.00	
GRAND TOTAL		:	\$ 13,877.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *00/07/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 days*
HL/S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT