

張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

India International Insurance
64 Cecil Street
#04 -05 IOB Building
Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

Dear Sir/Madam


05.07.2021

RE: THIRD PARTY CLAIMS FOR FBS291C AGAINST YOUR
INSURED GBK1996M, ACCIDENT ON 02.07.2021 ALONG
PASIR PANJANG ROAD TOWARDS TELOK BLANGAH

YAMAHA AEROX GDR155R CVT

DESCRIPTION	AMOUNT
1 HANDLE BAR	\$ 78.00 <i>bt</i> ✓
2 LEFT SIDE MIRROR	\$ 25.00 <i>ant</i> ✓
3 RIGHT SIDE MIRROR	\$ 25.00 <i>ant</i> ✓
4 BALANCER 1 SET	\$ 50.00 <i>ant</i> ✓
5 STEERING CONE	\$ 90.00 <i>del</i> ✓
6 FRONT BRAKE LEVER	\$ 28.00 <i>ant</i> ✓
7 UNDER BRACKET	\$ 280.00 <i>bt</i> ✓
8 FORK 1 SET	\$ 300.00 <i>bt</i> ✓
9 FRONT SIGNAL LEFT SIDE	\$ 45.00 <i>ant</i> ✓
10 HEAD LAMP	\$ 380.00 <i>ant</i> ✓
11 LEFT FRONT SIDE COVER	\$ 35.00 <i>ant</i> ✓
12 RIGHT FRONT SIDE COVER	\$ 35.00 <i>ant</i> ✓
13 LEFT FRONT SIDE BLACK COVER	\$ 48.00 <i>ant</i> ✓
14 RIGHT FRONT SIDE BLACK COVER	\$ 48.00 <i>ant</i> ✓
15 INNER LEFT FRONT SIDE BLACK COVER	\$ 48.00 <i>ant</i> ✓
16 INNER RIGHT FRONT SIDE BLACK COVER	\$ 48.00 <i>ant</i> ✓
17 RIGHT FOOT STEP COVER	\$ 48.00 <i>del</i> ✓
18 RIGHT SIDE LOWER BLACK COVER	\$ 45.00 <i>ant</i> ✓
19 RADIATOR COVER	\$ 35.00 <i>ant</i> ✓
20 EXHAUST PROTECTOR	\$ 55.00 <i>ant</i> ✓
21 MAIN STAND	\$ 75.00 <i>del</i> ✓
22 RIGHT REAR FOOTREST	\$ 65.00 <i>ant</i> ✓
23 RIGHT SIDE BLACK COVER	\$ 30.00 <i>ant</i> ✓
24 TOP BOX	\$ 200.00 <i>ant</i> ✓
25 LEFT TAIL COVER	\$ 58.00 <i>ant</i> ✓
	\$ 2,171.00
Less 10%	\$ 217.10
Sub Total	\$ 1,953.90

2171
1953.90



張 噴 漆
TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

Nett Item		
1 LABOUR	\$ 280.00	200
2 INSURANCE SEARCH	\$ 7.45	
3 TRANSPORT	\$ 70.00	50.
Sub Total	\$ 357.45	257.45
Total	\$ 2,311.35	

THANKS
TSP

Tanjin 97495749/62563561
WP' 6/7/21 @ 2:15pm
0.5 days
P/P Resurvey new parts
tanjin@lkkauto.com.


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

India International Insurance
64 Cecil Street
#04 -05 IOB Building
Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

06.07.2021

Dear Sir/Madam

RE: THIRD PARTY CLAIMS FOR FBS291C AGAINST YOUR
INSURED GBK1996M, ACCIDENT ON 02.07.2021 ALONG
PASIR PANJANG ROAD TOWARDS TELOK BLANGAH

Supplementary

- 1 METER COVER
- 2 FRONT WHEEL SHAFT
- 3 LAMP STAY

	\$ 45.00	am ✓
	\$ 25.00	ht ✓
	\$ 55.00	ht ✓
SUB-TOTAL	\$ 125.00	
LESS 10%	\$ 12.50	
TOTAL	<u>\$ 112.50</u>	

Tayfuni 97495749
7/7/21 210395

Thank you.

Teo Spray Painting

~~1953.90~~
~~257.15~~
~~112.50~~
~~2323.85~~
05 days

\$2,316.40 #