

Steve CLKK) L/S, 12 dys
6/7/21, 12-30pm My AL by CK141498

MOVA
Automotive Pte Ltd

Estimate

05/07/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SLD4944L

Veh Model :- VOLKSWAGEN SCIROCCO

Estimate# :- CK422032

Claim # :-

ACC. Date :- 02/07/21

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-008864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER / BR	1 PC	900.00	900.00
2.	REAR BUMPER LOWER GARNISH / CUT	1 PC	600.00	600.00
3.	REAR BUMPER REFLECTOR LH	1 PC	60.00	60.00
4.	REAR BUMPER REINFORCEMENT	1 PC	410.00	410.00
5.	REAR BUMPER RETAINER - CENTER	1 PC	85.00	85.00
6.	REAR BUMPER RETAINER - RH & LH	2 PC	42.00	84.00
7.	REAR BUMPER CLIPS / nec	10 PC	4.00	40.00
8.	REAR END PANEL (REPAIR)	1 PC		
9.	REAR EXHAUST SILENCER / BT	1 PC	820.00	820.00
10.	REAR EXHAUST MOUNTING	2 PC	55.00	110.00
11.	REAR FENDER RH / DO	1 PC	1,180.00	1,180.00
12.	REAR FENDER COWLING RH	1 PC	145.00	145.00
13.	REAR FENDER PROTECTOR RH / CUT	1 PC	100.00	100.00
14.	REAR FENDER INNER TRIM RH - CHECK	1 PC		
15.	REAR QUATER GLASS MOULDING RH / X	1 PC	360.00	360.00
16.	CENTER PILLAR RH / X R	1 PC	1,080.00	1,080.00
17.	FRONT DOOR RH / DO	1 PC	1,500.00	1,500.00
18.	FRONT DOOR WEATHERSTRIP RH	1 PC	215.00	215.00
19.	FRONT DOOR OUTER MOULDING RH / BT	1 PC	75.00	75.00
20.	FRONT DOOR PROTECTOR RH / CUT	1 PC	110.00	110.00
21.	FRONT DOOR OUTER HANDLE RH / CUT	1 PC	265.00	265.00
22.	FRONT DOOR OUTER HANDLE BRACKET RH - CHECK	1 PC		
23.	FRONT DOOR NOB RH - CHECK	1 PC		
24.	FRONT DOOR MIRROR HOUSING RH / BR	1 PC	175.00	175.00
25.	FRONT DOOR MIRROR COVER RH / BR	1 PC	145.00	145.00
26.	FRONT DOOR MIRROR SIGNAL RH / BR	1 PC	100.00	100.00
27.	FRONT DOOR GLASS REGULATOR RH / BT	1 PC	315.00	315.00
28.	FRONT DOOR GLASS REGULATOR MOTOR RH - CHECK	1 PC		
29.	FRONT DOOR LOCK RH	1 PC	315.00	315.00
30.	FRONT DOOR INNER TRIM RH - CHECK	1 PC		
31.	FRONT FENDER RH / DO	1 PC		
32.	FRONT BUMPER RETAINER RH / BR	1 PC	450.00	450.00
33.	FRONT BUMPER (REPAIR) / X R	1 PC	35.00	35.00
34.	FRONT BUMPER CLIPS / X	1 PC		
35.	REAR WHEEL BEARING RH - CHECK	10 PC	4.00	40.00
36.	REAR LOWER ARM RH - CHECK	1 PC		
LIST TOTAL S\$				9,714.00
10% DISCOUNT S\$				-971.40
				8,742.60
SPECIAL NET ITEMS :				
1.	REAR NUMBER PLATE / MIS	1 PC	40.00	40.00
2.	REAR QUATER GLASS SEALANT / nec	1 PC	40.00	40.00
3.	REAR SPARE RIM RH / CUT	1 PC	1,050.00	1,050.00
4.	REAR TYRE RH / X	1 PC	250.00	250.00
SPECIAL NET TOTAL S\$				1,380.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

05/07/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 141498
Veh # :- SLD4944L
Veh Model :- VOLKSWAGEN SCIROCCO
Estimate# :- CK422032
Claim # :-
ACC. Date :- 02/07/21
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR : TO CUT/WELD REAR END PANEL, REAR FENDER RH, CENTER PILLAR RH, KNOCK AND STRAIGHTEN FRONT DOOR PILLAR RH, REAR FENDER INNER PANEL RH . REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	1400		1,800.00
	SPRAY PAINT FRONT BUMPER , FRONT FENDER RH, FRONT DOOR PILLAR RH, FRONT DOOR MIRROR COVER & FRONT DOOR RH, CENTER PILLAR RH, REAR FENDER RH, REAR FENDER INNER RH, TAILLAMP PANEL RH, REAR END PANEL, REAR BUMPER	1200		1,600.00
	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	30		80.00
	REMOVE & REPLACE REAR QUATER RH & CHECK WATER LEAKAGE	30		100.00
	REMOVE & REPLACE FENDER INNER TRIM, REAR SEAT ASSY, ROOF LINING, UPHOUSTERY, FLOOR CARPET (photo)	80		180.00
	REMOVE & REPLACE UNDER CARRIAGE SUSPENSION RH	?		150.00
	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION			30.00
	REMOVE & REPLACE PETROL TANK, HOSE, PIPE, GARNISH (photo)	50		80.00
	COMPUTER WHEEL ALIGNMENT			60.00
	DIAGNOSE AND RESET SYSTEM AFTER REPAIR	100		200.00
	RUST PROOF AFFECTED AREAS	30		100.00
	LABOUR TOTAL S\$			4,380.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088884-2

Estimate

05/07/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 141498
Veh # :- SLD4944L
Veh Model :- VOLKSWAGEN SCIROCCO
Estimate# :- CK422032
Claim # :-
ACC. Date :- 02/07/21
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 14,502.60

GST @ 7 % 1,015.18

AMOUNT DUE S\$ 15,517.78

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: