

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A / Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) _ \$ + RS. _ \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

9/7/11 4/5 @ 2300 confirmed with Sebastian

Rear & Rear w/scratched Mark.

T K LEE AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

GBF8700E

Mike Joslin

Not Authorised
R&R

6/7/21

Take photo After repair

4/5 \$2300

2 days.

ESTIMATE

DATE : 06/07/2021

VEHICLE NO : GBG7207P

MAKE/MODEL : TOYOTA HIACE

ACC DATE : 02/07/2021

PARTICULAR		UNIT PRICE	AMOUNT
QTY		\$\$	\$\$
	<u>LIST PRICE</u>		
1	1 REAR WINDSCREEN <i>shattered</i>	\$ 1,150.95	\$ 1,150.95 ✓
2	1 REAR GATE <i>30530</i>	\$ 2,162.70	\$ 2,162.70 ✓
3	1 REAR GATE LOGO <i>11</i>	\$ 80.10	\$ 80.10 X
4	1 REAR GATE INNER TRIM <i>11</i>	\$ 550.35	\$ 550.35 X
5	1 REAR GATE RUBBER <i>11</i>	\$ 405.45	\$ 405.45 X
6	1 REAR WIPER ARM <i>11</i>	\$ 180.10	\$ 180.10 X
7	1 REAR WIPER BLADE <i>11</i>	\$ 85.30	\$ 85.30 X
8	1 REAR WIPER ARM COVER <i>11</i>	\$ 35.30	\$ 35.30 X
9	1 REAR WIPER BLADE MOTOR <i>11</i>	\$ 549.00	\$ 549.00 X
			\$ 5,199.25
	LESS - 25%		\$ 1,299.81
	TOTAL		\$ 3,899.44

SPECIAL NETTS ITEM

1	1 REAR WINDSCREEN SPONGE <i>her</i>	\$ 30.00 ✓
2	1 REAR WINDSCREEN SEALANT <i>her</i>	\$ 80.00 40
3	1 REAR GATE STICKER ' 70KM / H ' <i>her</i>	\$ 25.00 10
4	1 REAR GATE STICKER ' HIACE ' <i>her</i>	\$ 25.00 ✓
5	1 REAR GATE STICKER ' 8 PAX ' <i>her</i>	\$ 25.00 10
6	1 REAR GATE STICKER ' 1250 KG ' <i>her</i>	\$ 25.00 ✓
	TOTAL	\$ 210.00

LABOUR CHARGES :

1	WIRE CHECKING	\$ 30.00 20
2	R/R REAR WINDSCREEN	\$ 120.00 100
3	TRANSFER REAR GATE PARTS	\$ 100.00 60
4	LABOUR	\$ 300.00 100
5	PAINTING	\$ 250.00 200
	TOTAL	\$ 800.00

LKK Auto Consultants hence notify

the Receiver of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 4,909.44

p. 3050-80
25%
2288.1