



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Norwiah Binte Muhamad	Cust No/Name /Ms Norwiah Binte Muhamad
BLK 464 UPPER SERANGOON RD	Reg No/Reg Date SLQ5107L / 13/07/201
#04-1217	Date In/Mileage / 0
SINGAPORE 530464	Chassis No MMBSTA13AHH006040
Contact No Mobile: 90675897	Engine No 3A92UGB2389
	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	02/07/2021/ 13:32	TLE	261 / Edwin Caina	12652

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT188000 RENEW FRT BUMPER & LHF FENDER 2 X 649				1280 2560.00
E PNT198000 RESPRAY FRT BUMPER & LHF FENDER 2 X 550				1100 1650.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				280.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				80.00
M SUNDRY SUPPLY BODY PNL SEALANT				80.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING				50 80.00
M SUNDRY RE-SEAL WEEKEND PLATE				120.00
M SUNDRY Sundries				20 50.00
M FACE,FR BUMPER / CR4	1.00	706.00	00.00	706.00
M GARNISH,FR BUMPER,LH X nn	1.00	127.00	00.00	127.00
M BRACKET,FR BUMPER,LH / BR	1.00	13.00	00.00	13.00
M CLIP,FR BUMPER / nec	12.00	4.00	00.00	48.00
M FENDER,FR LH / nn	1.00	500.00	00.00	500.00
M SHIELD,FR WHEELHOUSE,LH ? X nn	1.00	98.00	00.00	98.00
M HEADLAMP ASSY,LH / BR	1.00	663.00	00.00	663.00
M EMBLEM ECO / nec	1.00	17.00	00.00	17.00

SURVEYOR NAME: Steve CLKK 21/7/21, 11:00am

SURVEYOR SIGNATURE: Wil PL

DATE: PIP, My Bel SJ

Confirm & accepted by

REMARKS: 4 djs

7% GST on	Nett 7152.00	7,152.00
		500.64

Total Payable 7,652.64

Link to Consultants hence notify
the repairer of the following:

- To survey before/after spray painting
- To replace damaged part(s) during resurvey
- To replace part(s) not to confirmation

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.