

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Rparthiban, Theerthan

Date: 08 Jul 2021

Preliminary Advice

Vehicle No	: SMC9617S	Accident Date	: 06/07/2021
Make	: CITROEN C4	Policy No.	: 1800089003
Assignment Date	: 06/07/2021	Excess	: S\$300.00
Date of Inspection	: 06/07/2021	Est. Duration of Repair	: 12
Inspection At	: CYCLE & CARRIAGE FRANCE PTE LTD (PANDAN GARDENS) (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 16,941.80
Revised Amount	:S\$ 14,311.80
Check Items (Estimated)	:S\$ 716.80
Total	:S\$ 15,028.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 81,000.00
COE / PARF Rebate	:S\$ 40,635.00

Salvage Value	:S\$
Margin for Repair	:S\$ 40,365.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :