

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/06/2021
TP Veh Reg No: SMV9346Z

Estimate No: EST2100175
Date: 01 Jul 2021
Veh Reg No: SJU8808E
Make/Model: M.BENZ E250 CGI A
Chasis No: WDD2120472A415119
Reg. Date: 10/08/2011
Your Ref No: SMV9346Z

Estimate Repair Cost to Vehicle No :SJU8808E

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC REAR BUMPER	2,309.00	
2	1 PC REAR BUMPER REFLECTOR - RH	38.00	
3	1 PC REAR LOWER BUMPER	389.00	
4	1 PC REAR BUMPER RH MOULDING CHROME	410.00	
5	1 PC EXHAUST CHROME COVER RH	314.00	
6	1 PC REAR BUMPER SIDE RETAINER RH	108.00	
7	1 PC TAIL LAMP - RH	889.00	
8	2 PCS REVERSE SENSORS	626.00	
		5,083.00	
	Less 10%	508.30	4,574.70
Special Net			
9	1 SET REAR BUMPER CLIPS	60.00	
		60.00	60.00
Labour			
10	1 TO CHECK WIRING	50.00	
11	1 (REAR) TO SPRAY PAINTING	500.00	
12	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00	
13	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
		1,230.00	1,230.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/06/2021
TP Veh Reg No: SMV9346Z

Estimate No: EST2100175
Date: 01 Jul 2021
Veh Reg No: SJU8808E
Make/Model: M.BENZ E250 CGI A
Chasis No: WDD2120472A415119
Reg. Date: 10/08/2011
Your Ref No: SMV9346Z

Estimate Repair Cost to Vehicle No :SJU8808E

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 5,864.70
	Add GST @ 7%		410.53
	Total Amount Payable		S\$ 6,275.23

TOTAL: SINGAPORE DOLLAR SIX THOUSAND TWO HUNDRED SEVENTY FIVE AND CENTS
TWENTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE