

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

AIG

Name : Medusa Motor

Accident Date : 26-Jun-21

Vehicle No : FBQ5784A

Vehicle Model : Yamaha Aerox
GDR155R CVT

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy	\$ 980.00 x <i>on 120</i>
1	Fork under bracket	\$ 190.00 x
1	Front sport rim	\$ 550.00 x
1	Front brake disc	\$ 180.00 <i>λ</i>
1	Front rim shaft	\$ 52.00 x
1	Headlamp	\$ 550.00 <i>ant-</i>
1	Side mirror (1 set)	\$ 120.00 <i>ant-</i>
1	Handle-bar	\$ 135.00 ?
1	Handle-bar balancer (1 set)	\$ 98.00 <i>ant-</i>
1	Hand grip (1 set)	\$ 78.00 <i>ant-</i>
1	Brake lever	\$ 104.00 <i>ant-</i>
1	Front signals (1 set)	\$ 160.00 <i>ant-</i>
1	Front side inner cover	\$ 250.00 <i>ant-</i>
1	Front center lower cover	\$ 185.00 <i>ant-</i>
1	Footstep panel	\$ 285.00 <i>ant-</i>
1	Footstep panel lower cover	\$ 340.00 <i>dis-</i>
1	Belt cover	\$ 175.00 <i>ant-</i>
1	Air filter cover	\$ 125.00 <i>ant-</i>
1	Exhaust assy	\$ 680.00 x
1	Exhaust protector	\$ 48.00 x
1	Main stand	\$ 180.00 <i>bt-</i>
1	Fairing cover (1 set)	\$ 1,450.00 <i>ant-</i>
		\$ 6,915.00
	Less 10%	\$ 691.50
		\$ 6,223.50

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Medusa Motor

Accident Date : 26-Jun-21

Vehicle No : FBQ5784A

Vehicle Model : Yamaha Aerox
GDR155R CVT

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	\$	28.00	X
2	Fork oils	\$	30.00	✓
2	Fork oil seals	\$	56.00	✓
1	Steering cone	\$	120.00	?
1	Front slider (1 set)	\$	180.00	bt
1	Rear box	\$	520.00	cut 300
1	Rear box bracket	\$	180.00	X
1	Rear tyre	\$	120.00	X
1	Sticker (1 set)	\$	120.00	rel 60
		\$	1,354.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/No. Labour

1	To provide towing service	\$	60.00	✓
2	To provide wiring and reset headlamp focusing	\$	80.00	30
3	To repair body frame	\$	380.00	200? photo
4	To provide labour	\$	450.00	200
		\$	970.00	

Grand Total

\$ 8,547.50

Singapore Dollars: Eight Thousand Five Hundred Forty-Seven and Cents: Fifty only

EROFIA MOTOR TRADING PTE LTD

Tanfah 97475749 / 62563561
'WP' 7/7/21 2 430
Lumpsum Resurvey after repair
tanfah@lkhauto.com
5 days