



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD

3 ANSON ROAD #15-00

SPRINGLEAF TOWER

SINGAPORE 79909

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGP6281Z

MAKE MODEL : MAZDA 3

REFERENCE : 1AP-202106-20

DOA : 26-Jun-21

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*BONNET	1	\$ 1,090.80	X
*BONNET STOPPER LH	1	\$ 111.20	X
*BONNET STOPPER RH	1	\$ 111.20	X
*BONNET RUBBER FRONT	1	\$ 127.50	X
*BONNET RUBBER REAR	1	\$ 122.40	X
*BONNET HINGE LH	1	\$ 145.20	X
*BONNET HINGE RH	1	\$ 145.20	X
*BONNET LOCK ASSY	1	\$ 288.00	X
*FRONT BUMPER	1	\$ 976.20	de
*FRONT BUMPER REINFORCEMENT	1	\$ 690.60	X
*FRONT BUMPER SIDE RETAINER LH	1	\$ 128.40	X
*FRONT BUMPER SIDE RETAINER RH	1	\$ 128.40	X
*FRONT BUMPER LOWER GRILLE	1	\$ 220.60	X
*FRONT BUMPER LOWER SPOILER	1	\$ 580.00	X
*FRONT BUMPER FOG LAMP WITH COVER LH	1	\$ 371.10	X
*FRONT BUMPER FOG LAMP WITH COVER RH	1	\$ 371.10	X
*FRONT GRILLE ASSEMBLY	1	\$ 392.20	X
*FRONT BRACE PANEL	1	\$ 139.70	X
*FRONT SUPPORT PANEL	1	\$ 566.00	X
*HEADLAMP LH	1	\$ 975.90	X
*HEADLAMP RH	1	\$ 975.90	ang

\$ 8,657.60

2080.50

LESS 20% \$ 1,731.52

1664.40

SUBTOTAL \$ 6,926.08

BALANCE C/F \$ 6,926.08

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 6,926.08	
*FRONT BUMPER CLIPS	1	\$ 50.00	30 net
*FRONT NUMBER PLATE WITH CASING	1	\$ 100.00	X
*FRONT GRILLE CLIPS	1	\$ 50.00	X

SUBTOTAL \$ 200.00

30

BALANCE C/F \$ 7,126.08

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 79909
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGP6281Z
MAKE MODEL : MAZDA 3
REFERENCE : 1AP-202106-20
DOA : 26-Jun-21
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 7,126.08			
TO REMOVE, REFIT AND TRANSFER FRONT BUMPER COMPONENT	1	\$ 150.00	K 77
TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - FRONT	2	\$ 150.00	30
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR - FRONT	3	\$ 150.00	K 17
TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	4	\$ 100.00	x 44
TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	5	\$ 1,000.00	250
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	6	\$ 1,500.00	200

SUBTOTAL \$ 3,050.00

430

GRAND TOTAL \$ 10,176.08

1664.40

30

430

2124.40

1/5 \$1700, 2days #

Tanfah 97495749/62563561
WP 12/7/21 @ 11:05
1/5 Resurvey after repair
tanfah@lkkauto.com.
2days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: