

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21007409/Uqf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Date:	19/07/2021	
			Code	AGI	
1.					
	Insured Veh.	SKR 5380U	Veh. Inspected	SKU 2897A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010787/HA	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	07/07/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	KIA CARENS (A)	c.c	1999	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KNAHU813MG7128658	Colour	BROWN	
	Odometer	68070 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/07/2021	Inspection Date	08/07/2021	
	Survey held at	TAN LIM MOTOR PTE LTD			
		NO.1 DEFU LANE 6 SINGAPORE 539365			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: