

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No : SH 8813B DOA: 06.07.21
 Make : HYUNDAI
 Model : IONIQ

Date: ###
 Insurance: TOKIO
 MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT RH DOOR ASSY			\$1,797.20
1	REAR RH DOOR ASSY			\$1,789.90
1	FRT FH FENDER EMBLEM			\$26.60
1	FRT DOOR MOULDING RH			\$110.10
	SUB TOTAL			\$3,723.80
	LESS 20%			\$744.76
	DISCOUNTED TOTAL			\$2,979.04
	FRT DOOR COMFORTDELGRO LOGO		NET	\$75.00
	REAR DOOR APPS LOGO		NET	\$80.00
				\$155.00
	Labour Charge			
	PANEL BEATING		\$25	\$800.00
	SPRAYPAINT		\$50	\$1,000.00
	TRANSFER DOOR PARTS		120-	\$240.00
	Merimen fee \$11 net ✓			
	TOTAL LABOUR			\$2,040.00
	ESTIMATE TOTAL		1506	\$5,174.04

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be

2979.04

Tanpin 9749 5749

WP 7 @ 7/21 @ 5pm

Plp Resny before paint

03 days

tanpin @ thk auto.com

155
1506
\$4640.04, 3 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: