

Hui Zhen (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Wednesday, 1 September 2021 4:56 PM
To: Hui Zhen (LKK Auto)
Subject: RE: GBK 3711E Surveyed by Taufikh

Dear Hui Zhen,

Audit check done for GBK3711E without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)
Sent: Wednesday, 1 September, 2021 3:13 PM
To: Simon Ho (LKKAuto)
Subject: RE: GBK 3711E Surveyed by Taufikh

Dear Simon,

For your reaudit.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto)
Sent: Friday, 9 July 2021 2:57 PM
To: Hui Zhen (LKK Auto)
Subject: RE: GBK 3711E Surveyed by Taufikh

Dear Hui Zhen,

Audit check done for GBK3711E, found some parts prices need verification.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)

Sent: Friday, 9 July, 2021 2:26 PM

To: Simon Ho (LKKAuto)

Subject: GBK 3711E Surveyed by Taufikh

Dear Simon,

For your audit.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)