



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0544/2021/GW
DATE : 6-Jul-21
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,
13 days - ok - Jy - 25 Sep 21

OWNER'S NAME : MR CHUE ZHENG YANG
ADDRESS : 19 ENG KONG ROAD
SINGAPORE 596144
TELEPHONE : HP +65 92322548
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210046282
VEHICLE NO : **SMZ 6918 Y**
MODEL CODE : AUDI E-TRON SPORTBACK AVANCED 50 QU
MODEL YEAR : 12/5/2021
ENGINE NO : -
CHASSIS NO : WAUZZZGE9MB030088
MILEAGE : 1710 KM
DATE IN : 3-Jul-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jul-21
PLACE OF ACCIDENT : INTERSECTION OF TOH TUCK ROAD & TOH TUCK TERRACE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 6918 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO DEACTIVATE AND RE-ACTIVATE HIGH VOLTAGE SYSTEM FOR VEHICLE.	S/N \$	480.00		
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	300.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,200.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT BUMPER, LOWER SPOILER, RHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,000.00	\$	1,800.00
6	TO CARRY OUT PRE & POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 8,544.00	\$	4,164.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 6918 Y

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY			S/NETT	REMARKS
1	FRONT BUMPER	1	\$	2,724.00	\$	2,179.20
2	FRONT BUMPER FIXING PARTS	1	\$	631.00		
3	PLASTIC FOAM STRIP	1	\$	120.00		
4	FRONT BUMPER GRILLE LOWER CENTER	1	\$	254.00		
5	FRONT BUMPER GRILLE CENTER	1	\$	153.00		
6	FRONT BUMPER CLOSING ELEMENT CENTER	1	\$	222.00	\$	177.60
7	FRONT BUMPER CLOSING ELEMENT LOWER CENTER	1	\$	210.00		
8	FRONT AIR INLET RH	1	\$	91.00		
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$	807.00		
10	FRONT BUMPER SPOILER RH	1	\$	157.00	\$	131.60
11	FRONT BUMPER OUTER DUCT RH	1	\$	51.00	\$	40.48
12	FRONT BUMPER INNER DUCT RH	1	\$	39.00	\$	31.20
13	FRONT BUMPER TRIM RH	1	\$	58.00	\$	46.00
14	FRONT BUMPER DUCT RH	1	\$	120.00	\$	95.60
15	FRONT BUMPER GUIDE SECTION RH	1	\$	44.00	\$	35.12
16	FRONT SENSOR	1		TBC		
17	FRONT SENSOR SEAL RING	4	\$	14.00		
18	FRONT FENDER RH	1	\$	2,201.00	\$	1,760.80
19	FRONT FENDER ATTACHMENT PARTS	1	\$	249.00		
20	FRONT HEADLIGHT SEAL RH	1	\$	53.00		
SUB TOTAL SPARE PARTS		:	\$	8,198.00	\$	4,497.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 6918 Y

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY			S/NETT	REMARKS
		<i>c/f</i>			\$	4,497.60
21	FRONT FENDER BRACKET RH	1	\$	65.00	\$	51.92
22	FRONT FENDER BRACKET RH FRONT	1	\$	10.00		
23	FRONT FENDER BRACKET RH CENTRE	1	\$	14.00		
24	FRONT FENDER SUPPORT ELEMENT RH	1	\$	40.00		
25	FRONT FENDER INNER BRACKET RH	1	\$	16.00		
26	FRONT WHEEL HOUSING LINER RH	1	\$	275.00		
27	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	98.00		
28	FRONT BUMPER SPOILER RH	1	\$	95.00	\$	75.60
29	FRONT BUMPER BRACKET RH	1	\$	77.00		
30	LED HEADLIGHT RH	1	\$	8,142.00	\$	6,513.60
31	LED WITH HEAT SINK RH	1	\$	1,231.00		
32	LED HEADLIGHT POWER MODULE RH	1	\$	758.00		
33	LED HEADLIGHT HOSE RH	1	\$	29.00		
34	LIFT CLYLINER FOR HEADLIGHT WASHER SYSTEM	1	\$	236.00		
35	HOSE FOR HEADLIGHT WASHER SYSTEM	1	\$	96.00		
36	FRONT FENDER INSCRIPTION ' E-TRON'	1	\$	106.00	\$	84.80
37	FRONT WHEEL COVER LH RH	2	\$	1,030.00	\$	827.20
38	FRONT BUMPER COVER RH	1	\$	102.00		
39	FORNT BUMPER COVER	1	\$	105.00		
40	STICKER FOR WARNING SIGN	1	\$	19.00		
41	SUPPLEMENTARY			\$ 1,405.00	\$	1,157.76
42	SUNDRIES			\$ 300.00	\$	18.48
TOTAL SPARE PARTS		:		\$ 22,447.00	\$	13,226.96
TOTAL LABOUR CHARGES		:		\$ 8,544.00	\$	4,164.00
GRAND TOTAL		:		\$ 30,991.00	\$	17,390.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-25/08/21



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0544/2021/GW
Date 13-Jul-21
Service Advisor CHANG
Pages 1 of 1
Regn No SMZ 6918 Y
Model No AUDI E-TRON

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT FENDER BRACKET - RH	\$ 133.00	\$ 106.40
2	FRONT REINFORCEMENT - RH	\$ 35.00	\$ 29.36
3	FRONT BUMPER BRACKET - RH	\$ 430.00	\$ 344.00
4	FRONT BUMPER IMPACT PROTECTION - LOWER	\$ 807.00	\$ 678.00
GRAND TOTAL		\$ 1,405.00	\$ 1,157.76

For Premium Automobiles Pte Ltd

 Authorised Signature