

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21007462/c
	8 SHENTON WAY AXA TOWERSING			Date:	08/07/2021
				Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8816A	Veh. Inspected	k	SLB 8383P
	Policy No.		Coverage (\$)		0.00
	Claim No.	S1M03D1S	Excess (\$)		0.00
	Assign From	ANG Richard	Assign Date		08/07/2021
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer - Steering				
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	02/07/2021	Inspection Dat	e	08/07/2021
	Survey held at	SZE KANG AUTOMOBILE SPRAYING SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT . SINGAPORE 568047			
5a.		Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

08.07.2021 Dear Richard, we refer to your assignment this morning, we have contacted the work shop and spoke with Mr Anthony on 08.07.2021 at about 11.45am. He informed us that vehicle has started repair. Hence do beinformed that we have not conduct the survey of this vehicle. Thanks - Meng Yan