

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 19/20/20/VC10/310542 Date: 27<sup>th</sup> July 2021

Our Ref: CS1/LPM21007464/Etce2

## M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank No. 6 Jalan Sultan Sulaiman 50000 Kuala Lumpur, Malaysia

Dear Sir / Madam.

## **EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGJ 33U**

INSURED VEHICLE: JQN 3125 ACCIDENT DATE: 27/02/2020

We thank you for your instruction on 08/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGJ 33U from M/s United Appraisal And Management Pte Ltd.
- b) Final Repair Bill of SGJ 33U from M/s Carsmith Private Limited.
- c) Singapore Accident Statement and Police Report of Vehicles SGJ 33U.
- d) Colour damaged vehicle photographs of SGJ 33U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SGJ 33U

Make & Model : Porsche Macan PDK CYP E5

Year of Registration : 2017

Chassis Number : WP1ZZZ95ZHLB10194

Engine Capacity : 1984 cc

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.