



Your Ref : CMTD2101985/THE

Date: 10th Aug 2021

Our Ref : CS/SMO21007493/Uuf3e2

M/s Sompo Insurance Singapore PL

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBE 9931D
INSURED VEHICLE: YP 8270D
ACCIDENT ON 01/07/2021**

Instruction was received to inspect the vehicle Reg. No. FBE 9931D. The inspection was conducted on 09/07/2021 at the premises of M/s JC Motors Pte Ltd, 13 Kaki Bukit Road 4 #01-16, Bartley Biz Centre, Singapore 417807.

The following vehicle information was recorded:

Registration Number	: FBE 9931D
Make/Model	: Daelim B-Bone 125 Auto
Year of Registration	: 2010
Body Colour	: Black / Red
Chassis Number	: KMYSA8BLSBC000702
Engine Capacity	: 125 cc

The vehicle sustained damages at the front portion and o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 5,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 3,165.00)
Nett Liability	<u>S\$ 1,835.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.