

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

FRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21007499/T1tce2
	8 SHENTON WAY AXA TOWERSING			Date:	16/07/2021
	ATTN: YVONNE A	NG		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 6101K	Veh. Inspected		SMN 9762Y
	Policy No.		Coverage (\$)		0.00
	Claim No.	S1M03DEM	Excess (\$)		0.00
	Assign From	YVONNE ANG	Assign Date		09/07/2021
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FREED HYBRID	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	GB71101020	Colour		GREY
	Odometer	241654 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	185/65 R15	IPLUS		6 mm
	L/H Front Tyre	185/65 R15	IPLUS		6 mm
	R/H Rear Tyre	185/65 R15	IPLUS		6 mm
	L/H Rear Tyre	185/65 R15	IPLUS		6 mm
4. Description of Damages					
	THE VEHICLE SUS UNDERCARRIAGE	BODY AND			
5. General Information					
	Accident Date	09/07/2021	Inspect Date / 1	Γime	09/07/2021 (04:00 PM)
	Survey held at	APEX MOTORING			
	25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800.				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		9 Worki	ng Days

Report Ref No. CS3/ASM21007499/T1tce2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.