

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email:kentsengcarservices@gmail.com

M/s AIG Asia Pacific Insurance Pte Ltd DATE 19.07.2021
AIG Building, 78 Shenton Way #07-16, CAR NO YP 2902 D
Singapore 079120 MAKE Mitsubishi Canter

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : SMC 9617 S

Pc	Pcs	FEB21EA20596	UNIT PRICE	AMOUNT
1	pc	Right side sliding door panel (front side) <i>(side panel) for s/n 1000</i>		\$2,500.00 <i>price?</i>
		Labour for jacking, knocking right side sliding door lower bar, dismantle & replace right side sliding door panel (front side).		\$600.00 <i>300</i>
		To respray right side sliding door panel.		\$800.00 <i>400</i>
		Lettering, logo draqing & advertisement on right side sliding door panel. <i>AM</i>	<i>s/n 300</i>	\$1,100.00 <i>price?</i>
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				

Resue
Hp 90010068
3 days
4/3
19/07/21 @ 1630
Resue after repair

Page 1 of 1 Total \$5,000.00

Susan Lim
KENT SENG CAR SERVICES.

S/N - 1300
L - 700
T - 2000
20%
1600
1/1,600