



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6496L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER "HONDA" LOGO	NECESSARY	48.40	48.40
1	FRONT BUMPER SIDE RETAINER RH	DAMAGED	33.10	33.10
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	33.10	-
1	HEADLAMP RH (UNIT ONLY)	CRACKED	1,299.60	912.00
1	HEADLAMP BULB RH	NOT NECESSARY	59.90	-
1	HEADLAMP LOWER BRACKET RH	BENT	49.10	49.10
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	637.50	-
1	FRONT FENDER INNER SHIELD RH	DEFORMED	195.40	195.40
1	SIDE MIRROR MECHANISM RH (NPA)	NOT NECESSARY	-	-
1	SIDE MIRROR COVER RH (NPA)	NOT NECESSARY	-	-
1	SIGNAL LAMP,SIDE MIRROR RH (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-471.22	-247.60
			1,884.88	990.40
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIP @\$5.00 (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER (SN)	TORN	1,800.00	800.00
10	FRONT FENDER INNER SHIELD CLIP @\$5.00 (SN)	NECESSARY	50.00	30.00
1	FRONT SPORTS RIM RH (SN)	CUT	550.00	380.00
1	FRONT TYRE RH (SN)	NOT NECESSARY	450.00	-
			2,900.00	1,240.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	300.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		600.00	400.00
	ANTI-RUST UNDERCOATING.		50.00	30.00
			1,330.00	760.00
	GRAND TOTAL		6,114.88	2,990.40

Report Ref No. CS/AGI21007519/Aqf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	-----------------

Report Ref No. CS/AGI21007519/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.