



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|--|--------------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: RAJESWARY | | Ref: CS3/INC21000253/Gqf3e2-1 Date: 05/08/2021 Code: INC | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SMF 9429C | Veh. Inspected | SJZ 287J |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1116075-001 | Excess (\$) | 0.00 |
| Assign From | INCOME | Assign Date | 12/07/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | VOLKSWAGEN JETTA 1.4 | c.c | 1390 |
| Engine No. | HIDDEN | Year of Reg. | 2010 |
| Chassis No. | WVWZZZ1KZAM139173 | Colour | GREY |
| Odometer | 164868 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 205/55 R16 | FALKEN | 6 mm |
| L/H Front Tyre | 205/55 R16 | FALKEN | 6 mm |
| R/H Rear Tyre | 205/55 R16 | FALKEN | 6 mm |
| L/H Rear Tyre | 205/55 R16 | FALKEN | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 03/01/2021 | Inspection Date | 06/01/2021 |
| Survey held at | GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |