

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD		Ref: CS/SMR21007523/Auf3		
60 WOODLANDS INDUSTRIAL PARK		Date: 12/07/2021		
E4SINGAPORE 757705		Code: SMR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1991C	Veh. Inspected	GBH 3333D	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/07/21/2015	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	12/07/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/07/2021	Inspection Date	12/07/2021	
Survey held at	SIN FATT DIESEL MOTOR COMPANY BLK 3020A UBI ROAD 1 #01-38 SINGAPORE 408714			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				