



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21007523/Auf3n2 Date: 09/10/2021 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1991C	Veh. Inspected	GBH 3333D
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/07/21/2015	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	12/07/2021
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI EVERY	c.c	658
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	DA17V820714	Colour	GREY
Odometer	59091 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/50 R15	KUMHO	6 mm
L/H Front Tyre	175/50 R15	KUMHO	6 mm
R/H Rear Tyre	175/50 R15	KUMHO	6 mm
L/H Rear Tyre	175/50 R15	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/07/2021	Inspection Date	12/07/2021
Survey held at	SIN FATT DIESEL MOTOR COMPANY BLK 3020A UBI ROAD 1 #01-38 . SINGAPORE 408714		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	