



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM21001329/Gvf3e2-1 Date: 04/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHC 8138Z	Veh. Inspected	SCX 888T (SMY 5815Y)	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M0357N	Excess (\$)	0.00	
Assign From	CHAN KIAN CHUAN	Assign Date	12/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI EVO-9 GSR 2.0 M	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	CT9A0405965	Colour	YELLOW	
Odometer	92725 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	15/01/2021	Inspection Date	19/07/2021	
Survey held at	51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park			
Repairer	TEAMWORK GARAGE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	